

LKK:Jasper

not authorized

2/5 \$4100

3 days

take parts after repair

limited.

Page No. 1

VEHICLE NO. SKR 5922G

B M W 328i

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front bumper (A/M Modified) M Kit	DO/OE	3234.50	✓ 1800
1	Front bumper centre badge	new	98.00	✓ 65
2	Front bumper centre grille @472.50	SCR/CAR	215x2 945.00	✓ 430
2	Front bumper centre grille inner holder	11	250.00	X
1	Front bumper centre lower grille	11	328.00	X
1	Front bumper top strip cover rubber	11	102.00	X
1	Front bumper towing eye cover w/flap	11	112.00	X
2	Front bumper fog lamps @592.50	11	1185.00	X
2	Front bumper fog lamps cover @298.50	11	597.00	X
2	Front bumper headlamp washer cover	11	144.00	X
2	Front bumper headlamp washer nozzle @355	11	710.00	X
1	Front bumper reinforcement	11	980.00	X
1	Front bumper inner foam	TOIN	145.00	✓
2	Front bumper air duct RH & LH @122.50	11	245.00	X
2	RHS & LHS Headlamps @ 2283.40 xenon	O/S CNA	4566.80	1pc 2250
2	RHS & LHS Headlamps lower support @240.00	11	480.00	X
1	Bonnet	REPAIR 11	0.00	X
1	Front support panel centre top	REPAIR 11	0.00	X
1	Front support panel inner cover	11	298.00	X
1	RHS Front fender	REPAIR 11	0.00	X
			14420.30	
less			5% 721.02	5% 500
			13699.29	
SPECIAL NETT ITEMS				
1	Front bumper Lip Spoiler (bodykit) w/diffuser	11	980.00	X
1	Front licence plate	Self	50.00	} 40
1	Front licence plate base		75.00	
TOTAL PARTS			14804.29	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-4740

5%

2-4803

S.N 40

L-620

-5163

200

4130.

VEHICLE NO. SKR 5922G B M W 328i

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00 —	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired (bonnet and RHS Fender)	900.00 —	300
3	To remove and refix wirings at front damaged areas, check for proper function and focus headlamp beam	200.00 —	20
4	To clear fault code (with BMW diagnostic computer) and reset to specifications	350.00 —	11X
	Labour Total :	2450.00	
	TOTAL (PARTS & LABOUR):	17254.29	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts