

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATEInsurance Company: MS FIRST CAPITAL INSURANCE LIMITED
(MOTOR CLAIMS DEPARTMENT)Address: NO36, ROBINSON ROAD, #16-01
CITY HOUSE, S(068877)

Telephone: 65073848 Fax: 65073849

Email: motorclaims@msfirstcapital.com.sg

Make/Model: HYUNDAI AVANTE

Date: 26.05.2020

Chassis No: KMHD841CMLU996841

Vehicle No: SMP7358P

Date/Time of Accide: 26.05.2020/ 0905

Reg date: 14.10.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	FRONT BUMPER <i>to m</i>	1	\$ 658.20	\$ ✓ 658.20
2	FRONT BUMPER TOP RUBBER SEAL <i>new</i>	1	\$ 85.20	\$ ✓ 85.20
3	FRONT BUMPER TOP BRACKET RH <i>excl</i>	1	\$ 98.60	\$ ✓ 98.60
4	FRONT BUMPER SIGNAL LAMP RH <i>excl</i>	1	\$ 165.80	\$ ✓ 165.80
5	FRONT BUMPER RETAINER RH <i>new</i>	1	\$ 86.90	\$ ✓ 86.90
6	FRONT BUMPER AIR GUIDE RH <i>excl</i>	1	\$ 125.80	\$ ✓ 125.80
7	FRONT BUMPER SIDE STRIP RH <i>excl</i>	1	\$ 92.60	\$ ✓ 92.60
8	FRONT BUMPER SIDE COVER RH <i>excl</i>	1	\$ 98.60	\$ ✓ 98.60
9	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 295.60	\$ ✓ 295.60
10	FRONT BUMPER LOWER COVER RH <i>new</i>	1	\$ 202.30	\$ ✓ 202.30
11	FRONT ENGINE UNDER COVER <i>new excl</i>	1	\$ 356.80	197 \$ 356.80
12	FRONT BUMPER SPONGE <i>excl</i>	1	\$ 225.60	\$ ✓ 225.60
13	FRONT BUMPER LOWER STIFFENER <i>new</i>	1	\$ 175.20	\$ ✓ 175.20
14	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 589.50	\$ ✓ 589.50
15	FRONT BUMPER RADIATOR GRILLE <i>new</i>	1	\$ 1,082.90	\$ ✓ 1,082.90
16	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 202.50	\$ ✓ 202.50
17	FRONT SUPPORT PANEL <i>new</i>	1	\$ 987.50	\$ ✓ 987.50
18	FRONT WASHER TANK <i>new</i>	1	\$ 98.70	\$ ✓ 98.70
19	FRONT WASHER TANK MOTOR <i>new</i>	1	\$ 52.60	\$ ✓ 52.60
20	FRONT HEADLAMP RH <i>excl</i>	1	\$ 1,756.40	\$ ✓ 1,756.40
21	FRONT HEADLAMP BRACKET RH <i>excl</i>	1	\$ 98.60	\$ ✓ 98.60
22	FRONT BONNET <i>new</i>	1	\$ 1,971.20	\$ ✓ 1,971.20
23	FRONT BONNET INSULATOR <i>new</i>	1	\$ 385.90	\$ ✓ 385.90
24	FRONT FENDER RH <i>excl</i>	1	\$ 985.60	\$ ✓ 985.60
25	FRONT FENDER INNER COWLING RH <i>to m</i>	1	\$ 189.30	\$ ✓ 189.30
26	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 67.80	\$ ✓ 67.80
27	FRONT RIM RH <i>lt</i>	1	\$ 982.50	\$ 600/sv 982.50
28	FRONT KNUCKLE ARM RH <i>2</i>	1	\$ 423.50	\$ ✓ 423.50
29	FRONT WHEEL HUB BEARING RH <i>NR</i>	1	\$ 458.90	\$ ✓ 458.90
30	FRONT STABILIZER LINK RH <i>new</i>	1	\$ 158.90	\$ ✓ 158.90
31	FRONT STABILIZER BAR RH	1	\$ 298.70	\$ ✓ 298.70

32	FRONT STABILIZER BUSH RH <i>Free</i>	1	\$ 48.90	\$ X 48.90
33	FRONT ABSORBER RH	1	\$ 398.70	\$ X 398.70
34	FRONT ABSORBER TOP MOUNTING RH <i>New</i>	1	\$ 158.90	\$ X 158.90
35	STEERING RACK ASSY <i>New</i>	1	\$ 1,023.70	\$ X 1,023.70
36	FRONT LOWER ARM RH <i>New</i>	1	\$ 345.20	\$ X 345.20
Total List Price Cost				\$ 15,433.60
PARTS DISCOUNT 20%				\$ 12,346.88

4775
3823.20 SN: 600

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT FENDER INNER COWLING CLIPS <i>New</i>	1 SET	\$ 30.00	\$ X 30.00
2	FRONT BUMPER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ X 30.00
3	FRONT NUMBER PLATE WITH CASING <i>New</i>	1 SET	\$ 50.00	\$ X 50.00
4	FRONT ENGINE UNDERCOVER CLIPS <i>New</i>	1 SET	\$ 30.00	\$ X 30.00
5	FRONT HEADLAMP CLIPS <i>New</i>	1 SET	\$ 30.00	\$ X 30.00
6	FRONT ENGINE UNDERCOVER CLIPS <i>Repaired</i>	1 SET	\$ 30.00	\$ X 30.00
Total Special Nett Items				\$ 200.00

100

Labour Works/ Panel Beating Related Works		Quotation
Job Scope		
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN, STRAIGHTENED MEMBER		\$ 1,200.00
		500
Spray Painting		
Job Scope		
TO RESPRAY AFFECTED AREAS		\$ 1,200.00
		400
Others Cost (Accident Repair Related Expenses)		
Job Scope		
TO TUFFCOAT AFFECTED AREA		\$ X 150.00
TO REMOVE / REFIT FRONT CONDENSER AND TOP UP GAS FOR SUPPORT PANEL REPLACE		\$ X 120.00
LABOUR TO REMOVE / REFIT / REPLACE FRONT UNDERCARRIAGE		\$ X 200.00
TO PERFORM COMPUTERISED WHEEL ALIGNMENT BEFORE / AFTER		\$ 30 160.00
TO PERFORM COMPUTERISED FAULT CODE CLEARANCE AND SETTLING		\$ X 160.00
TO REMOVE/ REFIT WIRING CHECKS FOR HEADLAMP		\$ 30 150.00
Total Others Cost		\$ 940.00
GRAND TOTAL		\$ 15,886.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTODAY
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan

Direct Contact: +65 8782 7171

Email: allangoh.cas@gmail.com

Fax : 6509 9501

10/10

Allan Lj
1/s 27/05/20

04 Days

total 5533.20

1/s A.H.K.

A.H.K.