Not Nothering Renowy Bepalmy Eday

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel: 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

	No. of Many Control of the Control o		Date	:	<u>27/5</u>	/2020
24		**				
Quantity	Description/Particular		Unit	Amount		t
			Price			•
	REAR BUMPER		Bu 1	0.1	1700	00
	REAR BUMPER CHROME		1700	nu	170	00
	REAR BUMPER REFLECTOR			110	95	
	REAR EXHAUST CHROME				290	00
	REAR SENSORS			Su	280	00
			TOTAL		2535	00
			LESS 10			00
		The state of the s	1033 10		2281	50
	SPRAY PAINTING				250	
	LABOUR TO RENEW			350		00
	TO CHECK WIRING				350	00
					30	00
			Andrew Control			
		LKK Auto Consultants	hence notify			
		the Repairer of the foll • To resurvey before/afters	owing:			N.
		 To display damaged part(during resurve	v		li.
		Parts prices are subject to	confirmation			
		 Third party survey is on a No illegal modification(s) 	"Without Prejud	ce" basis		
		 Supplementary item(s) m 	ust be resurveve	d and	3011	50
eived the a	above goods in good order and condition	is subject to final approva Acknowledged by Repairer Signature: Date:	from Insurance	Company RC AU		