

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 02 Jun 2020

Preliminary Advice

Insured Vehicle No	: SDB2244S	Accident Date	: 22/05/2020
TP Vehicle No	: SGR171L	Assignment Date	: 27/05/2020
Make	: HONDA ACCORD	Est. Duration of Repair	: 5.00
Date of Inspection	: 28/05/2020		
Inspection At	: LYE DESIGNS (HQ) 10 AMK AUTOPOINT #04-04, ANG MO KIO INDUSTRIAL PARK 2A SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and undercarriage parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,256.37
Revised Amount	:S\$	12,717.33
Check Items (Estimated)	:S\$	7,149.87
Total	:S\$	19,867.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp