

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Name : H Mohamed Ashraf

Accident Date : 20-May-20

Vehicle No : FT7306X

Vehicle Model : Yamaha
RXZ

Estimated Repair Costs

Qty	Description <u>List Items</u>		Amount S(\$)
		<i>no f Authorized</i>	
1	Front fender	<i>2/5 #750</i>	CU \$ 65.00 ✓
2	Fork inner tubes	<i>4 days.</i>	SUC \$ 210.00 X
2	Fork outer tubes		11 \$ 220.00 X
1	Fork under bracket	<i>the ph. After repair</i>	SUC \$ 145.00 X
1	Front sport rim		11 \$ 250.00 ✓
1	Front rim shaft		CU \$ 38.00 ✓
1	Top cowlings		CU \$ 85.00 ✓
1	Windshield		SUC \$ 32.00 X
1	Lamp stay		11 \$ 50.00 X
1	Headlamp		CN \$ 70.00 ✓
2	Front signals		SUC \$ 80.00 X
1	Handle bar - L/H		BET \$ 68.00 ✓
1	Hand grip (1 set)		70.1 \$ 35.00 ✓
1	Handle bar end		11.5 \$ 18.00 ✓
1	Clutch lever		CN \$ 25.00 ✓
1	Meter assy		11 \$ 420.00 X
1	Fuel tank	<i>Local respray \$100</i>	BET \$ 400.00 X
1	Front footrest - L/H		CU \$ 32.00 ✓
1	Front footrest bracket - L/H		SUC \$ 55.00 X
1	Gear pedal		BET \$ 32.00 ✓
1	Rear footrest - L/H		CU \$ 28.00 ✓
1	Rear centre cowlings		CN \$ 35.00 ✓
1	Rear tailboard - L/H	<i>601</i>	CN \$ 70.00 ✓
			\$ 2,463.00
		Less 10%	\$ 246.30
			\$ 2,216.70

Special Net Items

1	Number plate (1 set)	<i>near ser</i>	\$ 28.00 10
2	Fork oils	11	\$ 30.00 X
2	Fork oil seals	11	\$ 56.00 X
1	Steering cone (1 set)	11	\$ 75.00 X
1	Front tyre	11	\$ 100.00 X
			\$ 289.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : H Mohamed Ashraf

Accident Date : 20-May-20

Vehicle No : FT7306X

Vehicle Model : Yamaha
RXZ

Estimated Repair Costs

S/No. Labour

1	To provide towing service	\$	50.00	✓
2	To check wiring and reset headlamp focusing	\$	80.00	X
3	To provide labour	\$	380.00	250
		\$	510.00	

Grand Total

\$ 3,015.70

Dollars: Three Thousand Fifteen and Cents: Seventy only



EROFIA MOTOR TRADING PTE LTD

350
760.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: