

Bifrost Auto Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **SMN 7209 S**Model: **AUDI Q3**Chassis No: **WAUZZZ8U4HR019745**Year of manufacturing: **2006**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper / <i>DD ? / OR</i>	\$ 1,444.50	\$ 1,444.50 /
2	1	Front Lower Bumper Lip <i>? / OR</i>	\$ 289.60	\$ 289.60 /
3	1	Front Bumper Retainer <i>? / OR</i>	\$ 79.00	\$ 79.00 /
4	1	Front Bumper Grille <i>X NM</i>	\$ 95.00	\$ 95.00 X
5	1	Front Bumper Grille Chrome <i>X NM</i>	\$ 815.70	\$ 815.70 X
6	1	Front Bumper Sponge <i>X NM</i>	\$ 84.60	\$ 84.60 X
7	1	Front Reinforcement <i>X NM</i>	\$ 497.60	\$ 497.60 X
8	1	LHS Headlamp <i>? / OR</i>	\$ 5,455.60	\$ 5,455.60 /
9	1	LHS Headlamp Nozzle <i>? / OR</i>	\$ 215.80	\$ 215.80 /
10	1	LHS Headlamp Nozzle Cover <i>X NM</i>	\$ 40.20	\$ 40.20 X
11	1	Front Bumper Fog Light Cover <i>/ CUT</i>	\$ 113.40	\$ 113.40 /
12	1	LHS Headlamp Bracket <i>? / OR</i>	\$ 81.60	\$ 81.60 /
13	1	Support Panel <i>? X NM</i>	\$ 789.50	\$ 789.50 X
14	1	Support Panel Top[Garnish <i>X NM</i>	\$ 95.20	\$ 95.20 X
15	1	LHS Bonnet Lock <i>X NM</i>	\$ 184.20	\$ 184.20 X
16	1	LHS Front Fender <i>X R</i>	\$ 587.20	\$ 587.20 X
17	1	LHS Front Fender Shield <i>X NM</i>	\$ 162.80	\$ 162.80 X
18	1	LHS Front Fender ARCH <i>? / OR</i>	\$ 210.60	\$ 210.60 /
19	1	Wiper Tank <i>? / CRG</i>	\$ 197.20	\$ 197.20 /
20	1	Radiator <i>X NM</i>	\$ 365.00	\$ 365.00 X
21	1	Condenser <i>X NM</i>	\$ 585.50	\$ 585.50 X

\$ 12,389.80-10% \$ 1,238.98Total for spare parts \$ 11,150.82

8087.30

- 19%

7278.57

Special Nett									
1	1 set	Front Bumper Clip	/ M	\$	61.00	\$	30 /	61.00	
2	10	RHS Front Fender Shield Clip	X NN	\$	5.00	\$		50.00	X

Total for SP	\$	111.00
Sub-Total for Parts :	\$	11,261.82

30

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-	\$	800.00 300
2		To putty and spray paint on all accident damage parts and other accident	\$	600.00 400
3		To check wiring system to facilitate repair and refit the same	\$	60.00 30
4		Apply rust proofing on the adjacent panels	\$	80.00 30
5		To conduct headlamp focus	\$	80.00 30
6		To supply under coating / putty on parts replaced	\$	50.00 X
7		To perform water seepage test after repair	\$	120.00 X

TOTAL AMOUNT :	\$	1,790.00	790
OVERALL COST:	\$	13,051.82	

Steve (LKK) ML ML
 28/5/20, 10.45am
 3 days
 LIS
 By AL My

P-7278.57
 M-30
 L-790
 8098.57
 LIS-6478.85
 = 6500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: