

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J**AAD2005-058***Not Authorised**61 Sep @ 1650hr*

Vehicle No.:

Chassis No.:

Vehicle Make:

27 MAY 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5542J

VF1ABL15AUC278894

RENAULT

LATITUDE

25.5.2020

AIG

15/8/2014

PART		LIST	
1	BUMPER COVER REAR	\$ <i>Bu</i>	561.70 —
1	BUMPER LOWER REAR	\$ <i>roll on</i>	411.90 —
1	BUMPER BRACKET CTR REAR	\$ <i>Sn</i>	98.10 X
1	BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i>	82.10 <
1	BUMPER RETAINER RH REAR	\$ <i>Sn</i>	59.80 A
1	BUMPER REFLECTOR RH	\$ <i>CM</i>	16.60 —
1	BUMPER BRACKET SIDE LH REAR	\$ <i>Sn</i>	80.80 X
1	BUMPER RETAINER LH REAR	\$ <i>Sn</i>	54.20 X
1	BUMPER REFLECTOR LH	\$ <i>Sn</i>	16.60 X
1	BUMPER BEAM REAR	\$ <i>Bu</i>	547.80 —
1	BUMPER BEAM BRACKET LH REAR	\$ <i>R</i>	114.50
1	BUMPER BEAM BRACKET RH REAR	\$ <i>R</i>	100.90
1	OUTER PANEL REAR (End Panel)	\$ <i>R</i>	745.80
1	OUTER PANEL REAR (End Panel) TRIM	\$ <i>Sn</i>	404.56
1	TAILLAMP RH	\$ <i>Sn</i>	313.10
1	TAILLAMP PANEL RH	\$ <i>R</i>	401.40
1	TAILLAMP LH	\$ <i>Sn</i>	401.40
1	TAILLAMP PANEL LH	\$ <i>R</i>	401.40
1	BOOT REAR	\$ <i>R</i>	1,677.20
1	BOOT FINISHER	\$ <i>Sn</i>	344.70
1	BOOT WHEATERSTRIP	\$ <i>Sn</i>	178.20
1	BOOT REFLECTOR LAMP LH	\$ <i>Sn</i>	277.70
1	BOOT REFLECTOR LAMP RH	\$ <i>Sn</i>	277.70
1	BOOT BADGE 'RENAULT'	\$ <i>na</i>	82.40
1	BOOT BADGE	\$ <i>na</i>	95.80
1	EXHAUST CAP REAR	\$ <i>Sn</i>	125.40
TOTAL		\$	7,871.76
10%		\$	787.18
		\$	7,084.58

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

AAD2005-058

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	68.00	—
1SET BUMPER BRACKET CTR CLIP	\$	35.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	25.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	35.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	25.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	35.00	X
1SET BUMPER LOWER REAR RIVET	\$	30.00	X
1SET BUMPER LOWER REAR CLIP	\$	68.00	✓
1 BOOT STICKER "Trans-cab"	\$	35.00	X
1 BOOT STICKER "6555-3333"	\$	35.00	X
1SET BOOT FINISHER CLIP	\$	35.00	X
1 TAILLAMP CLIP LH	\$	28.00	X
1 TAILLAMP CLIP RH	\$	28.00	X
1 Rear Bumper Protector	\$	120.00	30sm
1 REAR LICENCE PLATE WITH HOLDER	\$	100.00	X
TOTAL	\$	1,402.00	

TOTAL PARTS \$ 8,486.58**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	10h
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

AAD2005-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5542J

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *2001*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *4* 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *4* 170.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

Putty and spray painting of the affected portion.

\$ 6,000.00 *2201*

To repair and realign rear exhaust cap and exhaust pipe.

\$ *4* 170.00 *X***TOTAL \$ 14,340.00****Over All Total \$ 22,826.58****LUMP SUM (REPAIR DAY)***20 DAYS**2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: