COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC3710D

MAKE : HYUNDAI

DATE: 27. May. 2020

MODEL	: IONIQ	DOA:	26. May. 2020	<u>AIG</u>

MODEL	: IONIQ		DOA:	26. May. 2020	AIG
Qty	Parts Description		Туре	Unit Price	Amount
1	Front Bumper Cover $$	2)			\$418.30
1	Front Bumper Bracket – R	H XVV		21	\$28.00
	Front Bumper Top Bracket	t-RH ⊁nn			\$12.00
10	Front Bumper Clips 🛩 🥆	w		\$2.20	\$22.00
1	Headlamp − RH ××				\$1,993.65
1	Front Fender – RH PO –		9	ii	\$490.70
	Front Wheel Cover – RH				\$346.40
	Front Fender Emblem – RI	-			\$26.60
_					¥
		n.			
	onsultants hence notify	SUB TOTAL			\$3,337.65
the Repaire	r of the following: efore/after spray painting	LESS 20%		N	\$667.53
To display da	maged part(s) during resurvey	DISCOUNTED TOTAL			\$2,670.12
 Parts prices 	are subject to confirmation	DISCOUNTED TOTAL			\$2,070.12
	urvey is on a "Without Prejudice" basis dification(s) is allowed			eg a	
- Sunnlement	arv item(s) must be resurveyed and				
is subject to	final approval from Insurance Company	2 2			
Acknowledge	by Repairer				
Signature:					
Date:					
				a	\$-
			2		
	Labour Charge	Pancy	xx)	\$48	S
1	Panel Beating	Pa		45	\$700.00
1	Spray Painting Charge	28105/2	020 11	100 COM 840	
1	Wiring Charge		. Ock	ande & 30	\$80.00
1	Tuff Kote	Paragure	V	10 to \$430	\$80.00
1	Front Wheel Alignment	286227	-0000m	+ Ploto Xun	\$80.00
	J	\$ B	es	Tak	
		Panch 28105/2 Parasure 886227	BARRI	rang	
		TOTAL LABOUR			\$1,440.00
Me		ESTIMATE TOTAL			\$4,110.12
Lamy Ng					
	This is an initial estimate based	on a visual inspection of the	e ahove ve	hicle. The final renair o	uantum will
	be prepared after the vehicle is				
	be breharen arrei rue venicie is	Surveyed by a motor surve	yor appoin	ted by the moundine co	лпрапу.

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76870

Date/Time: 27.05.2020 15:12

Page : 1

Team:	ARC Repair	TP(CLSO)1		JOB	CARD	Sales Order	•	JC NO.: 3054	01094
STOMER	disk investeller Angerijk van Angerijk in de Sprinselijk de gelander Vereinstelle dit die des beschijd. Gebeur	et de la communicació de la commun La communicació de la communicació	City Pharth see 201 della lett gibbe loopeone	en Parte video meny lizer petro en el espera el conse	V/A DI	REGN NO.: SHC3	710D	MILEAGE	SINO HIPOTORIO PARTECIONI PARTECIONI POR CONTROLO CONTROL
STOMER NO.	701004		PTE	LTD	VARS	MAKE: HYUN	DAI	FUEL * E1/2.	F
DRESS 3	ingapore S	N MING DRIVE ore SINGAPORE 5757:	717			MODEL	Q(G3)	DATE/TIME IN 27.05.2020	
(R) 6	5508755	(O)		, ii *		YR OF MANU.	1.2020	TARGET DATE	
SCOUNT CARD	NO.		*		C	CHASSIS CODE KMHC	851CVLU19038	COMPLETION D	ATE/TIME:
				JOB DE	SCRIPTION				and the subjective of the control of
Accide NATURE	nt Date: 2 : 3P 26.05	6.05.2020 .2020 (C)						
	LA	BOR CODE			DESCI	RIPTION		FRONT	
	Ala	- Right	R	ont			LETT SIDE REAR		RIGHT SIDE
					· L :			8	
				(e) *					
a de ser engalement angles en application de se mothetische processor des processors des processors des proces	eer v. Tilligad pir mont siin hissoophi vennemis alli halki maa naheen siingolakeenee	errodeld date som en andeld kom flytte Salve steps steps som en en en en andeld blidde blit steps (C) en andeld	enterations, com restrictes has the constitution visual	elegtysphose (i.e., meletica) P20 oct. oc.			tanka kan anka kata an		i kada li masilini asandak sandharinki a rasiyiyadigi siyi
ECKED & PASSE	D OUT BY:			independent of the second			*		
	SERVICE ADVISOR		Ĭ.				CUSTOMER'S	SIGNATURE	
wledgement Slip)			* Exi	t Pass				
	HC3710D	LARRY		Approximation and a second	nicle No.:	SHC3710D			
of Service Advis	or Booseties	Signature/I	Date	Nar	me of Service Adv	isor	Date		