

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC3710D

DATE: 27. May. 2020

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 26. May. 2020

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover X(R)			\$418.30
1	Front Bumper Bracket – RH xun			\$28.00
	Front Bumper Top Bracket – RH xun			\$12.00
10	Front Bumper Clips xun		\$2.20	\$22.00
1	Headlamp – RH xun			\$1,993.65
1	Front Fender – RH PD			\$490.70
1	Front Wheel Cover – RH scr			\$346.40
1	Front Fender Emblem – RH rec			\$26.60
SUB TOTAL				\$3,337.65
LESS 20%				\$667.53
DISCOUNTED TOTAL				\$2,670.12
				\$-
Labour Charge				
1	Panel Beating		\$480	\$700.00
1	Spray Painting Charge		\$400	\$500.00
1	Wiring Charge		\$30	\$80.00
1	Tuff Kote		\$30	\$80.00
1	Front Wheel Alignment		xun	\$80.00
TOTAL LABOUR				\$1,440.00
ESTIMATE TOTAL				\$4,110.12
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Larry Ng

Ram(LKK)

28/05/2020 1145

Parasuram@lkkauto.com

88622711

88622711

(P/P)

3 days

\$480

~~\$480~~

\$400

\$30

\$30

~~\$30~~

xun

