

Not Authored
1/1/2018

CANDY

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHD178E - AIG

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD178E - CANDY
KL1LA69RJB092009
CHEVROLET
EPICA 2.0
05.04.2017
AIG

PART

LIST

- | | | |
|----|---|--------------------------------|
| 1 | 1 | Front Bumper |
| 2 | 1 | Front Bumper Lower Absorber |
| 3 | 1 | Front Bumper Reinforcement |
| 4 | 1 | Front Bumper Retainer RH |
| 5 | 1 | Front Bumper Retainer LH |
| 6 | 1 | Front Bumper Lower Grille |
| 7 | 1 | Front Bumper Lower Stiffener |
| 8 | 1 | Bumper Fog Lamp Cover RH |
| 9 | 1 | Bumper Fog Lamp Cover LH |
| 10 | 1 | Front Fender RH |
| 11 | 1 | Front Fender LH |
| 12 | 1 | Front Fender Liner RH |
| 13 | 1 | Front Fender Liner LH |
| 14 | 1 | Bonnet |
| 15 | 1 | Bonnet Moulding |
| 16 | 1 | Bonnet hinge RH |
| 17 | 1 | Bonnet hinge LH |
| 18 | 1 | Centr' logo badge |
| 19 | 1 | Front Support Panel Assy |
| 20 | 1 | Headlamp RH |
| 21 | 1 | Headlamp LH |
| 22 | 1 | Radiator Grille (Grille A-Rad) |
| 23 | 1 | Radiator Grille Top Cover |
| 24 | 1 | Fan Blade(A/C) |
| 25 | 1 | Air Intercooler |
| 26 | 1 | Aircon Condenser |

\$	CRA	1,202.00	—
\$	CRA	180.00	—
\$		356.00	?
\$	D11	102.00	—
\$	D11	102.00	—
\$	Sm	78.00	X
\$	R	134.37	X
\$	Sm	32.40	X
\$	Sm	32.40	X
\$	R	837.60	X
\$	R	837.60	X
\$	Sm	47.00	X
\$	Sm	47.00	X
\$	R	1,250.00	X
\$	Sm	161.97	X
\$	R	36.00	X
\$	R	36.00	X
\$	Sm	60.00	—
\$	R	1,222.32	X
\$	Sm	816.00	X
\$	mg CRA	816.00	—
\$	CRA	367.00	—
\$	Sm	45.02	X
\$	Sm	536.00	X
\$	Sm	652.00	X
\$	Sm	600.00	X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD178E - AIG

CANDY

TOTAL	\$	10,586.68
10%	\$	1,058.67
	\$	9,528.01

Special Nett

- 1 1 Set Front Bumper Fastener Clip
- 2 1 Set Radiator Grille Top Cover Clip
- 3 1 Set Front licence plate with holder
- 4 1 Set Radiator Grille clip
- 5 1 Set Front Fender Liner clip LH
- 6 1 Set Front Fender Liner clip RH
- 7 1 Set Louver Cowl Top clip
- 8 2 Bonnet stopper

\$ *nc* 24.00 ✓
 \$ *nn* 10.00 X
 \$ *nc* 80.00 *25.00*
 \$ *nc* 35.00 ✓
 \$ *nn* 30.00 X
 \$ *nn* 30.00 X
 \$ *nn* 30.00 X
 \$ *nn* 15.00 X

TOTAL	\$	254.00
TOTAL PARTS	\$	9,782.01

To Check Electrical Lighting Concerned.
 Panel beating, knocking and straightening the
 necessary portion, remove and renewal of parts,
 adjust and realign the same

\$ 170.00 *200*
 \$ 2,700.00 *500*

Putty and spray painting of the affected portion.

\$ 2,800.00 *600*

To replace, refix and top up coolant for radiator

\$ *nn* 170.00 X

To dismantle and refit aircon assy and
 attachment, vacuum and charge-in-gas.

\$ *nn* 380.00 X

To rust-proofing of the affected areas.

\$ *nn* 170.00 X

Towing Fees

\$ *nn* 120.00 X

UKFA The Carfulltime has notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from UKFA

Repair Days
 Acknowledged by Repairer
 Signature: _____
 Date: _____

TOTAL	\$	6,510.00
Over All Total	\$	16,292.01

10 Days
2 1/2 days