

ASS. REC. BY:

REF:

TU 120005992Ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ6633P Yr Regn: 03, 17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (A)Make: Mer CLA 200 c.c. 1595Colour: Black A/C: Insured / Std / NI / NASp. Reading: 43284 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1179432N439752Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / A/Rim orTyre Size: F: 225/40 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 3 mmL/Bal. 4 mm L/Bal. 3 mmD.O.A. 25/5/20 D.O.I. 29/5/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/6 1 Rep & 50501 Car Panel

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fees _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ _____)

City Auto PTE LTD
01-58/60/62 Sector C, Blk 8 Sin Ming
Industrial Estate
575643

Insurer Reference: SLJ6633P TP III
Repairer Reference: 031732
Date calculated: 26/05/2020 5:38 PM

Full Report
Registration: SLJ6633P
Printed: 26/05/2020 5:43 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	India International Insurance
Printed by:	JASON QUAK	Currency:	SGD
Claim Reference:	SLJ6633P TP III	Date of Incident:	25/05/20
Estimated Repair Time:	7	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	CLA (X117)
Sub Model:	CLA 200
Model Sheet Number:	03 L6 73
Registration:	SLJ6633P

VIN number:
Odometer:

Model Specs

PARKTRONIC	TWO COAT METALLIC
------------	-------------------

Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas


All ☐
Underbody ☐

Not Authorized
Repair After Paint
6/5/20 & 7
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY		3.0	15.00
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		2.0	10.00
72-1640 01	RENEW R/R DOOR AND CONVERT PARTS INCLUDES: DOOR TRIM REMOVE AND REFIT AND ALL ATTACHED PARTS ASSEMBLE		32.0	160.00
60-2180 02	R + R ATTACHED PARTS OF THE REAR PANELLING FOR RENEWAL OF THE R/R WING INCLUDES: R + R ATTACHED PARTS IN THE REPAIR SECTION		62.0	310.00
63-1890 02	RENEW R/R SIDE PANEL CPL		105.0	525.00
88-8844 01	DIS + ASS REAR BUMPER (REMOVED)		5.0	25.00
88-8887 01	ADDITION TO DIS + ASS REAR BUMPER (VEHICLE WITH PARK ASSISTANT)		2.0	10.00
40-2410 01	R + R RIGHT REAR TYRE		3.0	15.00
40-2055 01	BALANCE R/R WHEEL		2.0	10.00
35-5741 01	R + R RIGHT REAR WHEEL HUB		10.0	50.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		22.60	226.0	1,130.00
Total of Labour				1,130.00

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
98-4415 01	R/R DOOR PAINTING STAGE I-M	11.0	55.00
98-1735 ZAX	REAR BUMPER COVER PAINTING STAGE I-M	8.0	40.00
98-7415 02	R/R SIDE PANEL PAINTING STAGE I-E	28.0	140.00
98-8980 ZAX	R/R WHEEL PAINTING	4.0	20.00
98-1710 ZAX	L/R INN PARKING SENS PAINTING STAGE II	1.0	5.00
98-1710 ZAX	R/R INN PARKING SENS PAINTING STAGE II	1.0	5.00
98-1710 ZAX	L/R OUT PARKING SENS PAINTING STAGE II	1.0	5.00
98-1710 ZAX	R/R OUT PARKING SENS PAINTING STAGE II	1.0	5.00
98-1710 ZAX	L/R CTR PARK SENSOR PAINTING STAGE II	1.0	5.00
98-1710 ZAX	R/R CTR PARK SENSOR PAINTING STAGE II	1.0	5.00
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	70.00
Total Paint		Hrs 7.10	WU 71.0 Price SGD 355.00

Material Cost - Paint

Surface-/Blend Paint
 New Part Painting (Weld)
 New Part Painting (Bold)
 Material-constant Metal
Total

Price SGD
 1.62
 79.00
 94.50
 13.47
 188.59

Spare Parts

				prices as at 2015-06-01	
Code	Description	Part Number	Part Source		Price SGD
2630	R/R BUMPER BRACKET	000 885 0411	OEM		R 70.00 X
1782	R/R DOOR	117 730 0205	OEM		Ry 1,510.00 ✓
1810	R/R DOOR SEAL	204 727 1187	OEM		mc 325.00 ✓
3482	R/R SIDE PANEL	117 630 2400	OEM	2780	By 2,855.00 2
9552	R/R WHEEL	246 400 0102 9040	OEM		Sm 950.00 X
9182	R/R WHEEL HUB	246 334 0006	OEM		in 395.00 X
3806	R/SIDE WINDOW	117 670 0212			0.00
3864	R/S WINDOW BOND KIT	000 989 4905			0.00
2583	REAR BUMPER COVER	117 880 0440 9999	OEM		Bul/Wt 1,030.00 ✓
f: OEM Parts					Savings 0.00
n: Non-OEM Parts					Subtotal 7,135.00
u: Used parts					Subtotal Discount(+20.00%) -1,427.00
Total					5,708.00

Extras

Code	Description	Price SGD
1000	Glass sealant Glass sealant	mc 40.00* 2
1001	Rear door rivet Rear door rivet	mc 36.00* ✓
1002	wheel alignment -	65.00* ✓
Total Extras		141.00

Final Calculation

	SGD	SGD
Parts	7,135.00	
Total Discount(+20.00%)	-1,427.00	
Total Parts		5,708.00
Labour Time Base 10 WU/h		
Total 226.0 WU X 50.00 SGD/h	1,130.00	
Total of Labour		1,130.00
Total Of Extras		141.00
Paint Work Time Base 10 WU/h		
Labour Cost 71.0 WU X 50.00 SGD/h	355.00	
Material Cost	188.59	
Total Paint Including Material		543.59
Repair Cost Excludes GST		7,522.59
GST (+7.0%)		526.58
Repair Cost Included GST		8,049.17

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.