

ASSIGNMENT

From:

Date:

Veh No:

SFA6608G

Yr Regn:

1117

Estimated Cost:

Type: *CA* M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

CA

To Inspect Vehicle No:

SFA6608G

Make:

Toyota harrier

C.C

1986

at Workshop m/s

Specialist

Colour

white

A/C: Insured / Std / NI / NA

of

Sp. Reading

70628

T/Radio: Insured / Std / NI / NA

Insured:

SKX6773G

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: *Good* / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: *Good* / Jammed / Leaked / Burnt or

(Client's Record)

Brake: *Good* / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:


F:

225/65R17

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8816

Front

6

Rear

6

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

12

days

Res.: Yes or No

D.O.A.

26/5/20

D.O.I.

28/5/20

Lum Sum:

2

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

187A

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Rep 1/16**LTA 53973 Bol by 7m**17/6/20 continued 4/5 #12.600 with hurling*

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFA6608G/2005054

27th May 2020

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident

Location

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: 26th May 2020

Pasir Ris Drive 1

Third Party Claim Vehicle No : SKX 6773 G
Repair Cost for Vehicle No : SFA 6608 G Toyota Harrier

Estimated Supply of Parts & Labours 1st item

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>body</i>	1	1,390.30	\$ 1,390.30 ✓
2	Rear boot emblem (logo) <i>new</i>	1	98.70	\$ 98.70 ✓
3	Rear boot reflector L&R <i>o/s cre</i>	2	412.20	\$ 824.40 1pc
4	Rear boot emblem garnish <i>cre</i>	1	1,120.60	\$ 1,120.60 ✓
5	Rear boot emblem (Harrier) <i>new</i>	1	96.70	\$ 96.70 ✓
6	Rear windscreen glass <i>new</i>	1	1,684.40	\$ 1,684.40 X
7	Rear windscreen moulding <i>new</i>	1	101.80	\$ 101.80 ✓
8	Rear lamp assy L&R <i>o/s cre</i>	2	555.20	\$ 1,110.40 1pc
9	Rear boot cover lock <i>new</i>	1	570.60	\$ 570.60 ✓
10	Rear boot cover catch <i>new</i>	1	68.40	\$ 68.40 X
11	Rear end panel <i>body</i>	1	715.10	\$ 715.10 ✓
12	Rear end panel inner garnish <i>D.S</i>	1	368.20	\$ 368.20 ✓
13	Rear end panel inner garnish clips <i>new</i>	1 set	20.00	\$ 20.00 X
14	Rear boot cover weather strip <i>new</i>	1	410.40	\$ 410.40 ✓
15	Rear bumper fascia (top) <i>D.S</i>	1	881.60	\$ 881.60 ✓
16	Rear bumper clips <i>new</i>	1 set	32.00	\$ 32.00 ✓
17	Rear bumper side retainer L&R <i>o/s cre</i>	2	90.00	\$ 180.00 1pc
18	Rear bumper sponge <i>new</i>	1	139.70	\$ 139.70 ✓
19	Rear bumper fascia lower <i>D.S</i>	1	440.90	\$ 440.90 ✓
20	Rear bumper reflector L&R <i>o/s cre</i>	2	71.70	\$ 143.40 1pc
21	Rear exhaust silencer assy <i>new</i>	1	982.70	\$ 982.70 X
22	Rear boot floor panel <i>body</i>	1	856.50	\$ 856.50 ✓
23	Rear fender inner garnish L&R <i>new / torn</i>	2	866.40	\$ 1,732.80 ✓
24	Rear boot floor garnish <i>crushed / torn</i>	1	852.30	\$ 852.30 ✓
25	Rear boot inner trim board <i>torn</i>	1	680.40	\$ 680.40 ✓
				\$ 15,502.30

Not Authorised
new
12 days
22/5/20
Take photo after repair
2/5 # 12,600

25%

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFA6608G/2005054

27th May 2020

No.	Particulars	Qty	Price	Amounts
				\$ 15,502.30
26	Rear boot board clips <i>u 1</i>	1 set	70.00	\$ 70.00 X
27	Rear chassis pillar RH <i>R</i>	1	982.60	\$ 982.60 X
28	Rear boot cover inner handle <i>To in</i>	2	78.40	\$ 156.80 ✓
29	Rear wheel splash shield RH <i>To in</i>	1	372.40	\$ 372.40 ✓
30	Rear floor panel top board <i>warped</i>	1	865.10	\$ 865.10 ✓
31	Rear side tray L&R <i>cna</i>	2	283.30	\$ 566.60 ✓
32	Rear inner tray L&R <i>en</i>	2	440.20	\$ 880.40 ✓
33	Rear boot lock cover <i>To in</i>	1	68.70	\$ 68.70 ✓
34	Rear floor panel reinforcement <i>R</i>	1	250.60	\$ 250.60 X
35	Rear floor cross member sub assy	1	580.40	\$ 580.40 X
36	Reverse camera(s/nett) <i>shut</i>	1	880.00	\$ 880.00 350 S.W
37	Reverse camera antenna(s/nett) <i>u 1</i>	1	380.00	\$ 380.00 X
38	Rear bumper sensor (s/nett) <i>shut</i>	1 set	380.00	\$ 380.00 200 S.W
39	Rear boot sealant(s/nett) <i>rei</i>	1	60.00	\$ 60.00 40 S.W
40	Rear boot end panel sealer(s/nett) <i>rei</i>	1	80.00	\$ 80.00 50 S.W
41	Rear boot floor panel sealer(s/nett) <i>rei</i>	1	80.00	\$ 80.00 ✓ S.W
				\$ 22,155.90

Labour Charges :-


	Amounts
Cut out, renew, knocking & welding rear boot cover, rear fender L&R, rear boot floor panel, rear end panel, rear chassis pillar RH, remove & install all damage parts, straighten rear chassis & re-align body	\$ 2,300.00 2000
Remove & install rear windscreen glass	\$ 140.00 120
Remove & install rear bumper sensor	\$ 100.00 50
Remove & install rear seats, carpets, upholstery & etc	\$ 280.00 100
Spray painting on damage parts	\$ 2,480.00 1480
Remove & refix rear exhaust silencer assy	\$ 380.00 60
Check all lighting after repairs	\$ 60.00 30
Tuff-kote on damage parts	\$ 200.00 100
Place vehicle on measuring bench	\$ 400.00 250
Labour Charge	\$ 6,340.00
Total Amount	\$ 28,495.90

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

P-14527.7 S.N-720
25% L-490
10895.77 15802.77
12694

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was approaching traffic junction of Pasir Ris Drive 1 on the center lane, traffic light was green in my favour. Opposite direction a van was turning right. As I slowing down and brake vehicle B (SKX 6773 G) from behind couldn't stop in time and collided onto the rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Sep 15 4 Series 435i Gran Coupe M-Sport At \$127.8k.



Low Mileage, Serviced At PML
With Records. Tip Top
Condition, 100% Accident Free
Lake View Credit StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

38 vehicles

Toyota Harrier

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Harrier		Any	Any	2017	Any	Any	Any	Available
	Toyota Harrier 2.0A Elegance Panoramic		\$91,800	\$11,330 /yr	21-Mar-2017	1,986 cc	43,175 km	SUV	Available
Rare Elegant Pearl White Harrier 2.0A With Panoramic Roof! Amazing Low Mileage Done 43175km. Totally Like New Condition. 1 Expat... Lake View Credit Pte Ltd Posted: 28-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									
	Toyota Harrier 2.0A Elegance		\$87,500	\$10,410 /yr	14-Jul-2017	1,986 cc	35,000 km	SUV	Available
100% Loan And Low-Interest Rate Just At 1.98% Pa! 1 To 1 Exchange With No Cash Top Up, High Trade In! 1 Owner Only! Low Mileag... Posted: 27-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									
	Toyota Harrier 2.0A Elegance Panoramic		\$95,800	\$10,900 /yr	13-Oct-2017	1,986 cc	40,000 km	SUV	Available
1 Owner Only, Brand New Condition, Warranty, 90% Loan Of The Car Price Can Be Arranged! Posted: 27-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									
	Toyota Harrier 2.0A Premium Panoramic		\$100,988	\$12,140 /yr	31-May-2017	1,986 cc	56,500 km	SUV	Available
Minimum 12 Months Warranty, STA Certified, Attractive Financing Rates And Easy Ownership With Supreme Cars Leasing! Beautiful Whit... Supreme Cars Ventures Pte Ltd Posted: 26-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									
	Edwin Garage - Specialist for Toyota Car repair, servicing & maintenance Edwin Garage Present to you the strongest team in car aircon, Japanese/ Korean car make and continental cars engine specialist. More info about this shop								
	Toyota Harrier 2.0A Elegance Panoramic		\$92,800	\$11,610 /yr	20-Mar-2017	1,986 cc	40,581 km	SUV	Available
95% Loan Of The Car Price Available! 1 Owner Only! Meticulously Well Maintained Unit With Clean And Neat Interior Assured! Low Milea... Creative Auto Posted: 26-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									
	Toyota Harrier 2.0A Premium Panoramic		\$92,500	\$11,470 /yr	09-Jan-2017	1,986 cc	-	SUV	Available
Elegant Brown SUV, Premium Model With Panoramic Moonroof And Electric Tailgate, "20" Inch Sports Rims, This Is Not A Rental/Limous... Prime Motor & Leasing Posted: 25-May-2020 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier									

[Compare](#)

https://www.sgcarmart.com/used_cars/listing.php?RGD=2017&MOD=Toyota Harrier&RPG=20&VEH... 28-May-20