

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX152G
CHEW YAM SONG
BLK 513 HOUGANG AVENUE 10
#12-247
SINGAPORE 530513
TEL : FAX :
PH : 91799988
ATTN :

ESTIMATE BILL

Number : EB00005482
Date : 28/05/2020
Case No : AD00011129
Vehicle No : SLX8062A
Chassis : JTJBC11A102041476
Year of Mfr : 2010
Policy No : 5117173702
Model : TOYOTA LEXUS
RX450H

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	TOTAL LOSS				
2	- REPAIR COST MORE THAN \$40,000.00				
	Sub Total				0.00
	Parts Total				0.00
<i>Not Authorised</i> <i>LKK</i> <i>28/5/20</i> <i>TOTAL LOSS</i> <i>MV \$33k?</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : ZERO AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		0.00
			GST 7.00%		0.00
			TOTAL		0.00

Date of accident : 26/05/2020 08:55 PM. Place : BEDOK RESERVOIR TOWARDS PIE NEAR BLK 705

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE