

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6216D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	833.20	833.20
10	REAR BUMPER CLIP @\$6.50 (CONSISTENT)	NECESSARY	65.00	30.00
1	REAR L/H BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	28.00	28.00
1	REAR L/H FENDER (CONSISTENT)	DENTED	843.80	843.80
1	REAR L/H FENDER INNER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	375.70	-
1	REAR L/H FENDER COWLING (CONSISTENT)	NOT NECESSARY	85.60	-
8	REAR L/H FENDER COWLING CLIP @\$6.50 (CONSISTENT)	NOT NECESSARY	52.00	-
1	REAR L/H FENDER INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	487.60	-
8	REAR L/H FENDER INNER TRIM BOARD CLIP @\$6.50 (CONSISTENT)	NOT NECESSARY	52.00	-
1	REAR L/H TAIL LAMP (CONSISTENT)	CUT	336.50	336.50
2	REAR L/H TAIL LAMP CLIPS @\$8.00 (CONSISTENT)	NECESSARY	16.00	16.00
1	REAR L/H TAIL LAMP PANEL (CONSISTENT)	NOT NECESSARY	169.20	-
1	REAR L/H TYRE (CONSISTENT)	NOT NECESSARY	350.00	-
	LESS 10% DISCOUNT		-	-208.75
			3,694.60	1,878.75
	SPECIAL NETT ITEMS			
1	REAR L/H RIM (CONSISTENT) (SN)	CUT	800.00	500.00
			800.00	500.00
	LABOUR			
	TO REMOVE & REAR RREFIT REVERSE SENSOR .		100.00	60.00
	TO REMOVE & REFIT CUSHION & TRIM BOARD .		280.00	80.00
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE.		150.00	80.00
	TOWING.	NOT NECESSARY	150.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR L/H FENDER INNER PANEL .		1,000.00	500.00
	SPRAY PAINTING.		800.00	500.00
			2,580.00	1,250.00

Report Ref No. CC4/ASM20006008/Aka3q2



Page No.:2 of 2

GRAND TOTAL	7,074.60	3,628.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		2,900.00

Report Ref No. CC4/ASM20006008/Aka3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.