



新德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

27-05-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA

Khanchana

Accident date: 27/05/2020

Estimated repair cost for vehicle no: SLP6216D MITSUBISHI ATTRAGE 1.2 CVT 17'

CHASSIS: MMBSTA13AHH005682

S/n	Qty	Items	U/price	Amount	
1	1	Rear Bumper <i>deformed</i>		\$833.20	✓
2	10	Rear Bumper Clip <i>de</i>	\$6.50	\$65.00	30
3	1	Rear L/H Bumper Side Retainer <i>new</i>		\$28.00	✓
4	1	Rear L/H Fender <i>Dented.</i>		\$843.80	✓
5	1	Rear L/H Fender Inner Panel <i>Repair</i>		\$375.70	+
6	1	Rear L/H Fender Cowling <i>3 NP</i>		\$85.60	+
7	8	Rear L/H Fender Cowling Clip <i>3 NP</i>	\$6.50	\$52.00	+
8	1	Rear L/H Fender Inner Trim Board <i>3 NP</i>		\$487.60	X
9	8	Rear L/H Fender Inner Trim Board Clip <i>3 NP</i>	\$6.50	\$52.00	X
10	1	Rear L/H Tail Lamp <i>LT</i>		\$336.50	✓
11	2	Rear L/H Tail Lamp Clips <i>new</i>	\$8.00	\$16.00	✓
12	1	Rear L/H Tail Lamp Panel <i>all new</i>		\$169.20	+
13	1	Rear L/H Rim <i>LT</i>		\$800.00	500 (SW)
14	1	Rear L/H Tyre <i>new</i>		\$350.00	+

Subtotal :- \$4,494.60

2087.50

S.N: 500

1878.75

Labour charges

To remove & rear refit reverse sensor

~~\$100.00~~ 60

To remove & refit cushion & trim board

~~\$280.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 80

Towing

~~\$1,000.00~~ 500

Panel beating

~~\$800.00~~ 500

Spray painting

Subtotal :- \$2,580.00

Total:- \$7,074.60

sealant
To remove windscreen.

total 3628.75

4/s: 2.9K.

05 days

2.9K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: