



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

Steve (LKK) *whl P/L*
29/5/20, 3.00pm
L/S
Ry AL sy
5 days

28 May 2020

OWNER : CHUA KAR WEE
ACCIDENT DATE: 26 MARCH 2020
REG NO. : SMD 362 E
MAKE/MODEL : MERCEDES BENZ GLA180

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Rear bumper / <i>BR</i>	\$ 1,385.00 /
1	Rear bumper side retainer / <i>BR</i>	\$ 75.00 /
1	Rear bumper side reverse sensor <i>X NAI</i>	\$ 355.00 X
1	Rear fender-L/H <i>X R</i>	\$ 2,255.00 X
1	Rear fender wheel arch garnish / <i>CUT</i>	\$ 325.00 /
1	Rear alloy wheel rim (<i>LH</i>) / <i>CUT</i>	\$ 1,780.00 <i>900</i> /
1	Rear wheel hub with bearing <i>?</i>	\$ 425.00
1	Rear shock absorber <i>X NAI</i>	\$ 520.00 X
1	Rear knuckle arm <i>X NAI</i>	\$ 1,265.00 X
1	Rear door-L/H / <i>DD</i>	\$ 2,025.00 /
1	Rear door rubber / <i>ML</i>	\$ 320.00 /
		\$ 10,730.00
	Less 10%	\$ 1,073.00
		\$ 9,657.00
SPECIAL NETT ITEMS		
1	Rear tyre <i>X NAI</i>	\$ 600.00 X
1	Rocker panel side skirt "S PLATINUM" / <i>CUT</i>	\$ 850.00 <i>500</i> /
		\$ 1,450.00
LABOUR CHARGES		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit rear reverse sensor.	\$ 150.00 <i>30</i>
3	To remove and refit rear undercarriage.	\$ 300.00 <i>150</i>
4	To conduct wheel alignment.	\$ 180.00 <i>60</i>
5	To remove, refit door fittings and replace damaged parts, transfer all	\$ 150.00 <i>80</i>
6	To apply undercoating.	\$ 100.00 <i>30</i>
7	Panel beating.	\$ 1,400.00 <i>500</i>
8	To re-spray painting on the affected areas.	\$ 1,200.00 <i>600</i>
		\$ 3,560.00

GRAND TOTAL :

\$ 14,667.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: