



**NINETEEN**  
AUTOWERKS

**NINETEEN AUTOWERKS PTE LTD**

Blk 13 Kaki Bukit Road 4 #01-05  
Bartley Biz Centre, Singapore 417807  
Tel: (65) 9270 5882  
nineteenautowerks@gmail.com

Steve (LKK) W/L P/L  
29/5/20, 3:00pm  
L/S  
By AL sy  
5 days

28 May 2020

OWNER : CHUA KAR WEE  
ACCIDENT DATE: 26 MARCH 2020  
REG NO. : SMD 362 E  
MAKE/MODEL : MERCEDES BENZ GLA180

**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear bumper / BR	\$ 1,385.00 ✓
1	Rear bumper side retainer / BR	\$ 75.00 ✓
1	Rear bumper side reverse sensor X NAI	\$ 355.00 X
1	Rear fender-L/H X R	\$ 2,255.00 X
1	Rear fender wheel arch garnish / CUT	\$ 325.00 ✓
1	Rear alloy wheel rim (LH) / CUT	\$ 1,780.00 900 ✓
1	Rear wheel hub with bearing ? / Jammed	\$ 425.00 ✓
1	Rear shock absorber X NAI	\$ 520.00 X
1	Rear knuckle arm X NAI	\$ 1,265.00 X
1	Rear door-L/H / DD	\$ 2,025.00 ✓
1	Rear door rubber / MC	\$ 320.00 ✓
		\$ 10,730.00
	Less 10%	\$ 1,073.00
		\$ 9,657.00
<u>SPECIAL NETT ITEMS</u>		
1	Rear tyre X NAI	\$ 600.00 X
1	Rocker panel side skirt "S PLATINUM" / CUT 500 ✓	\$ 850.00 500 ✓
		\$ 1,450.00
<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 30
2	To remove and refit rear reverse sensor.	\$ 150.00 30
3	To remove and refit rear undercarriage.	\$ 300.00 150
4	To conduct wheel alignment.	\$ 180.00 60
5	To remove, refit door fittings and replace damaged parts, transfer all	\$ 150.00 80
6	To apply undercoating.	\$ 100.00 30
7	Panel beating.	\$ 1,400.00 500
8	To re-spray painting on the affected areas.	\$ 1,200.00 600
		\$ 3,560.00

5455  
- 10%  
4909.50 ✓

**GRAND TOTAL :** \$ 14,667.00

P-4909.50  
N-500  
L-1480  
6889.50  
L/S-5511.60  
=5500

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: