

# RALLY PITSTOP

176 Sin Ming Drive  
#04-17 Sin Ming Autocare  
Singapore 575721  
Tel: 64516985  
Email: tar6985@hotmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature  
Date:

Date: 28-05-2020

To: Motor Claims Department  
MSIG Insurance

RE: Estimate repair cost of SLE4044D

Your Insured: SH45786C

Dear Sir/Madam,  
Vehicle No: SLE4044D  
Make Model: Honda / Vezel  
Date of accident: 27-05-2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

## Supplementary Parts

Qty	Description	Unit Price	TOTAL
1	Rear bumper <i>ven</i>		\$ 689.30
1	Rear bumper side retainer(RH) <i>SRU</i>		\$ 48.60
1	Rear right fender garnish <i>Cut</i>		\$ 256.90
1	Rear right door <i>ven</i>		\$ 897.30
1	Front right fender <i>Denture</i>		\$ 459.80
1	Front right fender garnish <i>Cut</i>		\$ 256.90
1	Head-lamp (RH) <i>Scratched</i>		\$ 585.10
1	Front bumper <i>ven</i>		\$ 658.60
1	Front bumper retainer (RH) <i>SRU</i>		\$ 48.60
1	Front right sport rim <i>Cut</i>		\$ 469.80
1	Front right knuckle <i>2x distron</i>		\$ 425.90
1	Front right wheel bearing <i>2x Distron</i>		\$ 225.90
1	Front right shock absorber <i>2x distron</i>		\$ 389.60
1	Front right lower arm <i>2x distron</i>		\$ 423.90
1	Front right stabilizer linkage <i>1x distron</i>		\$ 112.10
1	Front right Drive Shaft <i>Hnd</i>		\$ 957.90
	<b>Sub-total before discount</b>		\$ 6,906.20
	<b>Parts percentage discount 20%</b>		\$ 1,381.24
	<b>PARTS TOTAL</b>		\$ 5,524.96
	<b>LABOUR CHARGES &amp; MISC</b>		
1	Labour to dismantle & replaced the doors, fender and all accident damaged parts		\$ 1,300.00
2	Labour to putty & spray painting on the accident damaged parts & replaced parts		\$ 1,000.00
3	To provide under-coating		\$ 60.00
4	To do wheel alightment		\$ 60.00
5	Labour for checking all wiring		\$ 60.00
	<b>LABOUR TOTAL</b>		\$ 2,480.00
	<b>LABOUR &amp; PARTS TOTAL</b>		\$ 8,004.96

Regards,  
Terrence Lim

01/06/2020 @ 17:00pm  
NA Author  
L/Sun  
5 days  
Tya  
LKK Auto