



VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No. 198100320K

TAX INVOICE

PROVIDENCE AUTOMOBILE PTE LTD
Block 7 Kaki Bukit Road 1
#02-08 Eunos Technolink
Singapore 415939

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SJN5982R

ACCIDENT DATE : 13/02/2020

CLAIM No. : NOT AVAILABLE

INSURED VEH.No: FBH2168X

GST REG No. : M9-0000652-A

CUSTOMER ID : VACP0003

INVOICE No. : CL023244

INVOICE DATE : 10/04/2020

PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	30	1.00	\$ 30.00
Transportation	1	60.00	\$ 60.00
VAC Assessment Fee	1	240.00	\$ 240.00

GROSS AMOUNT \$ 330.00

GST @ 7% \$ 23.10

INVOICE AMOUNT \$ 353.10

This is a computer generated TAX INVOICE

No signature required

Cheque should be made payable to 'VICOM LTD'.

Sin Ming

385 Sin Ming Drive Singapore 575718
Tel: (65) 6455 5358 Fax: (65) 6455 8638

Bukit Batok

511 Bukit Batok St 23 Singapore 659545
Tel: (65) 6560 3312 Fax: (65) 6569 0722

Kaki Bukit

23 Kaki Bukit Ave 4 Singapore 415933
Tel: (65) 6741 6697 Fax: (65) 6749 2305

PROVIDENCE AUTOMOBILE PTE LTD
Block 7 Kaki Bukit Road 1
#02-08 Eunos Technolink
Singapore 415939



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 556358	Claim No.	: NOT AVAILABLE
Accident Date	: 13/02/2020	Claim Type	: THIRD PARTY
Assignment Date	: 19/02/2020	Policy No.	:
Survey Date	: 19/02/2020	Finalised Dt.:	09/04/2020
Survey Report Date	: 10/04/2020		
VEHICLE PARTICULARS			
Vehicle No.	: SJN5982R	Chassis No.	: ACR500083589
Registration Date	: 20/02/2009	Engine No.	: 2AZF216789
Make	: TOYOTA	Engine Cap.	: 2362CC
Model	: ESTIMA AERAS	Transmission	: AUTOMATIC
		Colour	: SILVER
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 111257KM		
TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH	215/55R17	GITI	6
FRONT LH	215/55R17	GITI	6
REAR RH	215/55R17	GITI	7
REAR LH	215/55R17	GITI	7
SURVEY CONDUCTED AT			
PROVIDENCE AUTOMOBILE PTE LTD Block 7 Kaki Bukit Road 1 #02-08 Eunos Technolink Singapore 415939			
REMARKS			
[1] Workshop Estimate : S\$ 9,516.50 [2] Our Adjustment : S\$ 3,800.00 [3] Repair Period : 6 days [4] We have not authorised repairs. This survey was carried out on without prejudice basis.			

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$)	VAC Adjustme (\$)		
1	1	Rear Bumper	Cracked / Deformed	588.50	588.50		
2	2	Rear Bumper Side Retainer Long X SVC	O/S Cracked / Deformed	96.30	X 48.15		
3	2	Rear Bumper Side Retainer Short X SVC	O/S Cracked / Deformed	74.90	X 37.45		
4	1	Tail Lamp Rh	Serviceable	406.60	0.00		
5	1	Rear Rh Fender x repair	Buckled	1849.80	x 1849.80		
6	1	Rear Rh Fender Protector	Deformed	165.85	165.85		
7	1	Rear Rh Inner Trim	Serviceable	80.25	0.00		
8	1	Rear Lh Inner Trim	Serviceable	80.25	0.00		
9	8	Rear Rh Fender Inner Trim Clip x svc	Cracked	34.24	x 14.00		
10	1	Rear Rh Inner Trim Fender 1/4 Glass Moulding x svc	Necessary	235.40	x 235.40		
11	1	Rear Rh 1/4 Glass Sealant x svc	Necessary	90.95	x 90.95		
12	1	Rear Rh Fender Side Shield	Serviceable	80.25	0.00		
13	1	Rear Rh Rim	Grazed / Dented	374.50	374.50		
14	2	Rear Rh Shock Absorber	Serviceable	535.00	0.00		
15	1	Rear Rh Tyre	Serviceable	251.45	0.00		
16	1	Rear Rh Axel	Serviceable	588.50	0.00		
17	1	Rear Rh Knuckle Arm	Serviceable	481.50	0.00		
18	2	Rear Rh Bearing X SVC	Jammed	438.70	X 438.70		
19	1	Rear Rh Door	Repair	197.95	0.00		
20	1	Rear Rh Door Protector	Necessary	144.45	144.45		
			Subtotal	1273.3	:	6795.34	3987.75
			Less 25 %	954.98		1698.84	996.94
			TOTAL		:	5096.50	2990.81
			TOTAL FOR SPARE PARTS		:	5096.50	2990.81

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustmer (S\$)
1	Labour	1600.00	400 800.00
2	Spray	1600.00	500 600.00
3	Rewire	100.00	✓ 20.00
4	Anit-rust	100.00	✗ 30.00
5	Upholstery	300.00	60 200.00
6	Alignment	100.00	✓ 60.00
7	R&r rear door under carriage	500.00	0.00
8	R&r rear right hand 1/4 glass	120.00	✗ 60.00
TOTAL FOR LABOUR AND SPRAY PAINTING		4420.00	1770.00

1040

Summary

Description	Workshop Estimate (S\$)	VAC Adjstment (S\$)
TOTAL FOR SPARE PARTS	5096.50	2990.81
TOTAL FOR LABOUR AND SPRAY PAINTING	4420.00	1770.00
TOTAL REPAIR COST	9516.50	4760.81

1994.98

-20%: 1600

5 days

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear o/s portion damage.


The damages seen during our survey were rear o/s door, rear o/s fender, rear o/s rim, rear bumper assy and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Providence Automobile Pte Ltd estimated a repair cost of S\$9,516.50. We adjusted it to S\$4,760.81.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$3,800.00.

The repairs would require a period of 6 working days.



Tommie Lim
for VICOM Ltd