

ASS. REC. BY: Marcus

REF:

CC6/AG20006021/UK93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: F3/2286at Workshop m/s BHM

of _____

Insured: SJR 28654

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$5500

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 3241

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: F3/2286Yr Regn: 5115

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: YamahaC.C. 124Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 9 2036

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LBPFE101000053403Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 2.75-18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. 24/5/20D.O.I. 29/5/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

not 228926/6/20 confirmed 2/5 \$1050 with Raymond

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$I☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

NO. : 36142

DATE : 27/05/2020

CLAIM NO. : 11560

POLICY NO. : MC/00791691

FROM : HASRIANAH

VEHICLE NO. : FBK2286Y

MAKE/MODEL : YAM / YBR125

not Arthur
2/s 1050
3 days
The photo after repair
29/5/20

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$23.00	23.00 <i>11</i> ✓
2	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00 <i>but</i> ✓
3	COVER TANK SIDE LH (RED) P/N: 60132	REPLACE	1.00	\$119.00	119.00 <i>2</i> ✓
4	COVER TANK SIDE RH (RED) P/N: 52956	REPLACE	1.00	\$119.00	119.00 <i>2</i> ✓
5	COWLING FRONT (RED) P/N: 52897	REPLACE	1.00	\$112.00	112.00 <i>one</i> ✓
6	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00	203.00 <i>but</i> ✓
7	FORK FRONT ASSY LH P/N: 53203	REPLACE	1.00	\$138.00	138.00 <i>100</i> ✓
8	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00	504.00 <i>300</i> ✓
9	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00	21.00 <i>500</i> ✓
10	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 <i>500</i> ✓
11	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	35.00 <i>cut</i> ✓
12	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	35.00 <i>cut</i> ✓
13	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00	97.00 <i>one</i> ✓

*36142 *

bizSAFE₃



Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00	119.00
15	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	56.00
16	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
17	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00
18	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	16.00
19	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	16.00
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
21	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	56.00
SUB TOTAL					\$1,944.00
GST @ 7 %					\$136.08
GRAND TOTAL (SGD)					\$2,080.08

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36142 *

bizSAFE₃



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 36142

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

DATE : 27/05/2020
CLAIM NO. : 11560
POLICY NO. : MC/00791691

FROM : HASRIANAH

VEHICLE NO. : FBK2286Y
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00 Disc %: 10.00	162.00
2	COWLING FRONT (RED) P/N: 52897	REPLACE	1.00	\$112.00 Disc %: 10.00	100.80
3	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00 Disc %: 10.00	182.70
4	FORK FRONT ASSY LH P/N: 53203	REPLACE	1.00	\$138.00 Disc %: 10.00	124.20
5	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$300.00	300.00
6	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00 Disc %: 10.00	18.90
7	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
8	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
9	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
10	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00 Disc %: 10.00	87.30
11	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00 Disc %: 10.00	107.10
12	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
13	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60

*36142 *

bizSAFE₃



Address: No. 6, Dafu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. : 2002-1-0363
ISO 9001 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40
15	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	16.00
16	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	16.00
17	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	19.00
18	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
SUB TOTAL					\$1,371.50
GST @ 7 %					\$96.01
GRAND TOTAL (SGD)					\$1,467.51

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*36142 *

bizSAFE₃

