



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 36142

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 27/05/2020
CLAIM NO. : 11560
POLICY NO. : MC/00791691

FROM : HASRIANAH

VEHICLE NO. : FBK2286Y
MAKE/MODEL : YAM / YBR125

*not added
all
2/55
3 days.
The photo of the
29/5/20*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$23.00	23.00 ?
2	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00 ?
3	COVER TANK SIDE LH (RED) P/N: 60132	REPLACE	1.00	\$119.00	119.00 x
4	COVER TANK SIDE RH (RED) P/N: 52956	REPLACE	1.00	\$119.00	119.00 x
5	COWLING FRONT (RED) P/N: 52897	REPLACE	1.00	\$112.00	112.00 —
6	CRASH BAR P/N: 35878	REPLACE	1.00	\$203.00	203.00 —
7	FORK FRONT ASSY LH P/N: 53203	REPLACE	1.00	\$138.00	138.00 —
8	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00	504.00
9	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$21.00	21.00 —
10	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 —
11	MIRROR LH P/N: 58099	REPLACE	1.00	\$35.00	35.00 —
12	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	35.00 —
13	MUDGUARD FRONT (RED) P/N: 45374	REPLACE	1.00	\$97.00	97.00 —

*36142 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	PROTECTOR EXHAUST P/N: 50024	REPLACE	1.00	\$119.00	SC 119.00
15	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	SC 56.00
16	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	7.00 14.00
17	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	RM 66.00
18	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	RM 16.00
19	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	REPLACE	1.00	\$16.00	RM 16.00
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$19.00	RM 19.00
21	TRANSPORT CHARGES P/N: 07169		1.00	\$56.00	35 56.00

SUB TOTAL

\$1,944.00

GST @ 7 %

\$136.08

GRAND TOTAL (SGD)

\$2,080.08

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*36142 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
 ISO 9001: 2015