



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3206L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOT RUBBER	TORN	181.00	181.00
1	REAR PANEL TOP GARNISH	SERVICEABLE	173.00	-
1	SET REAR PANEL TOP GARNISH CLIPS	SERVICEABLE	20.00	-
1	REAR PANEL	SERVICEABLE	897.04	-
1	SET REAR WINDSCREEN MLDG	SERVICEABLE	80.00	-
1	REAR BUMPER W CHROME	BADLY DENTED	1,526.20	899.00
14	REAR BUMPER CLIPS @\$5.00	NECESSARY	70.00	35.00
2	REAR BUMPER SIDE RETAINER @\$28.00	BENT	56.00	56.00
2	REAR BUMPER LAMP @\$97.00	SERVICEABLE	194.00	-
2	REAR BUMPER BRACKET @\$45.00	SERVICEABLE	90.00	-
2	REAR BUMPER CENTRE BRACKET @\$45.00	SERVICEABLE	90.00	-
	LESS 10% DISCOUNT		-	-117.10
			3,377.24	1,053.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER SENSOR (SN)	DENTED	350.00	200.00
1	SET REAR WINDSCREEN SEALANT (SN)	SERVICEABLE	50.00	-
1	SET REAR PANEL SEALANT (SN)	SERVICEABLE	50.00	-
			450.00	200.00
	<b><u>LABOUR</u></b>			
	REMOVE THE NECESSARY AFFECTED PARTS CUT / WELD REAR PANEL, STRAIGHTEN BOTH REAR CHASSIS AND REPLACE PARTS.		1,200.00	300.00
	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS.		980.00	400.00
	CHECK ELECTRICAL.	NOT NECESSARY	20.00	-
	TUFF KOTE.	NOT NECESSARY	50.00	-
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	40.00
			2,500.00	740.00
	<b>GRAND TOTAL</b>		<b>6,327.24</b>	<b>1,993.90</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,600.00</b>
---	--	--	-----------------

Report Ref No. CS3/AGI19012561/Gqf3e2-1

**XING GUO QIANG**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.