

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 28/05/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department** FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTRENT000053 Accident Date : 22/05/2020
Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	TAILGATE	1,475.20	bt ✓
1	TAILGATE WINDSCREEN SEAL	74.60	nei ✓
1	TAILGATE EMBLEM CENTRE	71.10	nei ✓
1	TAILGATE EMBLEM "VEZEL"	65.50	nei ✓
1	TAILGATE LOCK	342.20	?
1	TAILGATE RUBBER	224.30	?
1	REAR BUMPER	674.50	de ✓
10	REAR BUMPER CLIP	45.00	nei ✓
1	REAR BUMPER SIDE BRACKET LH	65.50	?

Date : 28/05/2020
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D19MTRENT000053 Accident Date : 22/05/2020
 Vehicle No : SML-4816-U Make & Model : HONDA VEZEL 1.5 (A) X
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER SIDE BRACKET RH	65.50	?
1	REAR BUMPER REFLECTOR LH	95.20	CRG ✓
1	REAR END PANEL	741.30	photo. ?
1	TOOL KIT COVER (SPONGE)	285.40	me ✓
1	SPARE TYRE PANEL		
	RESTORE		
	Sub Total	4225.30	
	Discount 20% On Parts	(845.06)	
	Special Nett Item		
1	WINDSCREEN SEALANT	60.00	ALC ✓
1	END PANEL SEALANT	40.00	?

Date : 28/05/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053

Accident Date : 22/05/2020

Vehicle No : SML-4816-U

Make & Model : HONDA VEZEL 1.5 (A) X

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REVERSE SENSOR	220.00	200 nm ✓
	Sub Total	320.00	
<u>Labour & Misc</u>			
	LABOUR TO CARRY OUT REAR REPAIR	700.00	600
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	30
	TO SPRAY PAINTING ON REAR AFFECTED AREA	600.00	500
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	30
	TO DETACH & RENEW REVERSE SENSOR	60.00	30
	TO TRANSFER TAILGATE FITTING	100.00	60

Date : 28/05/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTRENT000053

Accident Date : 22/05/2020

Vehicle No : SML-4816-U

Make & Model : HONDA VEZEL 1.5 (A) X

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & INSTALL REAR TAILGATE GLASS	150.00	120
	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT	100.00	60
	Sub Total	1785.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5,485.24

Remarks:

SUB TOTAL

GST 7.0 % 383.97

TOTAL 5,869.21

Surveyor's name:

Tanjah 97495749 tanjah@khaib.com
Lumpun

Principal's name: ETHOZ Group Ltd

Survey Date & Time:

29/5/20 @ 330 Resurvey after repair
05 days

PAGE : 4