

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1872S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOT LOGO (RENAULT)	NECESSARY	195.00	195.00
1	REAR BOOT LOGO (KANGOO MAXI)	NECESSARY	205.00	205.00
1	REAR BUMPER	CRUSHED	880.00	880.00
10	BUMPER CLIPS @\$8.00	NECESSARY	80.00	30.00
2	REAR PARKING SENSOR CENTRE @\$115.00	SHORTED	230.00	230.00
2	REAR PARKING SENSOR COVER CENTRE @\$28.00	CUT	56.00	56.00
1	REAR REINFORCEMENT	* CHECK	630.00	-
1	REAR BUMPER BRACKET CENTRE	* CHECK	430.00	-
1	(NPA)	TO REPAIR SEE LABOUR	-	-
1	SET FRONT GRILLE	* CHECK	580.00	-
1	FRONT BUMPER	CUT	900.00	900.00
10	FRONT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	FRONT BUMPER TOW COVER	CUT	75.00	75.00
1	FRONT REINFORCEMENT	* CHECK	690.00	-
1	SPONGE	* CHECK	300.00	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
2	AIR DEFLECTOR L+R (NPA)	NOT NECESSARY	-	-
1	RADIATOR (NPA)	NOT NECESSARY	-	-
1	CONDENSER (NPA)	NOT NECESSARY	-	-
1	FRONT HEADLAMP RH	NOT NECESSARY	780.00	-
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	60.00	-
1	FRONT HEADLAMP SUPPORT RH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-612.10	-260.10
			5,508.90	2,340.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BOOT STICKER (OUTDOOR AVENTURES) (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/SPF19021384/Eqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT STICKER (BUSINESS FOR GOOD) (SN)	NECESSARY	50.00	50.00
1	REAR BOOT STICKER (5 PAX) (SN)	NECESSARY	80.00	80.00
1	REAR BOOT STICKER (70 KM/H) (SN)	NECESSARY	80.00	80.00
1	REAR BOOT STICKER (BEST TEAM BUILDING TRAINING PROVIDER)(SN)	NECESSARY	90.00	90.00
1	REAR BOOT STICKER (FOCUS ADVENTURE) (SN)	NECESSARY	70.00	70.00
1	REAR BOOT STICKER (WWW.FOCUSADVENTURE.COM) (SN)	NECESSARY	120.00	120.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	FRONT NUMBER PLATE (SN)	DENTED	45.00	45.00
1	AIRCON GAS (SN)	NOT NECESSARY	50.00	-
1	COOLANT (SN)	NOT NECESSARY	50.00	-
			730.00	585.00
	<b>LABOUR</b>			
	TO REPAIR REAR BOOT L+R, REAR DOOR FENDER L+R.TO REPAIR FRONT SUPPORT PANEL. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHT ON ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT RH AND END PANEL.		750.00	500.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		600.00	300.00
	TO REMOVE & REFIX REAR PARKING SENSOR.		60.00	30.00
	TO REMOVE FRONT AIRCON CONDENSER & RADIATOR.	NOT NECESSARY	150.00	-
	TO INSPECT FRONT HEADLAMP WATER LEAKAGE TEST.		40.00	30.00
	TO RUST PROOF ON ACCIDENT DAMAGED PARTS.	NOT NECESSARY	80.00	-
			-	-
			-	-
			-	-
			-	-
			-	-
			-	-
			1,680.00	860.00
<b>GRAND TOTAL</b>			<b>7,918.90</b>	<b>3,785.90</b>

Report Ref No. CS/SPF19021384/Eqd3e2



<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,367.00 NETT)</b>			<b>3,785.90</b>
--	--	--	-----------------

Report Ref No. CS/SPF19021384/Eqd3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000**

**RECOMMENDED REPAIR DAYS : 4**

**WEEKEND : 2**

**TOTAL DAYS : 6**

**CHEN TSUE YEE**

**Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**