



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF19021384/Eqd3e2

ACCIDENT CLAIMS SECTION (SPORE POLICE  
FORCE) POLICE LOGISTICS BASE (PLB) 1  
HEMMANT ROAD SINGAPORE 438675

Date : 12-02-2020



ATTN : FRANKIE THAY

Code : SPF

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	QX 894J	<b>Veh. Inspected</b>	GBJ 1872S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	AEMD/105/009/2019/116	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	FRANKIE THAY	<b>Assign Date</b>	04/12/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	RENAULT KANGOO	<b>c.c</b>	1461
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	VF1FWT8H361486565	<b>Colour</b>	GREY
<b>Odometer</b>	19325	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	185/60 R14	MICHELIN	6 mm
<b>L/H Front Tyre</b>	185/60 R14	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	185/60 R14	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	185/60 R14	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	08/11/2019	<b>Inspection Date</b>	21/01/2020
<b>Survey held at</b>	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>4 Working Days</b>
--	-----------------------