

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

AAD2005-062

*Not Authenticated
L1 Syg @ 2950h*

Vehicle No.:

Chassis No.:

29 MAY 2020

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 620J

VF1ABL15AUC278507

RENAULT

LATITUDE

28.5.2020

III

27/6/2014

PART		LIST	
1	BUMPER COVER REAR	\$ Bu	561.70 ✓
1	BUMPER LOWER REAR	\$ Duller	411.90 ✓
1	BUMPER BRACKET CTR REAR	\$ Sn	98.10 X
1	BUMPER BRACKET SIDE RH REAR	\$ Sn	82.10 X
1	BUMPER RETAINER RH REAR	\$ Sn	59.80 X
1	BUMPER REFLECTOR RH	\$ Sn	16.60 X
1	BUMPER BRACKET SIDE LH REAR	\$ Sn	80.80 X
1	BUMPER RETAINER LH REAR	\$ Sn	54.20 X
1	BUMPER REFLECTOR LH	\$ Sn	16.60 X
1	BUMPER BEAM REAR	\$ B	547.80 ✓
1	BUMPER BEAM BRACKET LH REAR	\$ R	114.50
1	BUMPER BEAM BRACKET RH REAR	\$ R	100.90
1	BOOT REAR	\$ R	1,677.20
1	BOOT FINISHER	\$ Sn	344.70
1	BOOT WHEATERSTRIP	\$ Sn	178.20
1	BOOT REFLECTOR LAMP LH	\$ Sn	277.70
1	BOOT REFLECTOR LAMP RH	\$ Sn	277.70
1	BOOT BADGE 'RENAULT'	\$ nn	82.40
1	BOOT BADGE	\$ nn	95.80
1	BOOT STRUT LH	\$ Sn	145.10
1	BOOT STRUT RH	\$ Sn	145.10
1	BOOT HINGE LH	\$ R	254.20
1	BOOT HINGE RH	\$ R	253.80
1	BOOT TRIM BOARD	\$ Sn	611.00
1	BOOT LOCK	\$ R	246.60
2	BOOT RUBBER PLUG	\$ Sn	139.30
2	LICENCE PLATE LAMP	\$ Sn	26.30
1	TAILLAMP RH	\$ Sn	401.40
1	TAILLAMP PANEL RH	\$ R	401.40

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J**AAD2005-062**

1	TAILLAMP LH	\$	Sn	401.40	X
1	TAILLAMP PANEL LH	\$	Sn	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	B	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Sn	404.56	X
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	1,229.40	X
1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
1	SPARE TYRE BOARD	\$	Sn	680.90	X
1	EXHAUST CAP REAR	\$	Sn	125.40	X

TOTAL	\$	12,303.97
10%	\$	1,230.40
	\$	11,073.57

Special Nett

1SET PARKING AID	\$	Shot	700.00	400.00
1SET REAR BUMPER CLIP	\$	nn	69.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	nn	35.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	20.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	25.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	20.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	nn	25.00	X
1SET BUMPER LOWER REAR RIVET	\$	nn	30.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
2 END PANEL SEAM SEALANT	\$	nn	170.00	} X
1SET BOOT FINISHER CLIP	\$	nn	30.00	
1 BOOT STICKER "Trans-cab"	\$	nn	35.00	
1 BOOT STICKER "6555-3333"	\$	nn	35.00	
1 BOOT INNER TRIM CLIP	\$	nn	45.00	
1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
1 SPARE TYRE	\$	Sn	330.00	
1 TAILLAMP CLIP RH	\$	nn	25.00	
2 REAR WINDSCREEN SEALANT	\$	nn	150.00	
1 WINDSCREEN MOULDING	\$	nn	180.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	120.00	
1 TAILLAMP CLIP LH	\$	nn	25.00	
1 Rear Bumper Protector	\$	nn	120.00	
1SET Rear licence plate with holder	\$	Se	100.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

AAD2005-062

1SET END PANEL INSULATION PAD

\$ 200.00

TOTAL \$ 2,940.00**TOTAL PARTS \$ 14,013.57****LABOUR**

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 7,500.00 500

To supply and re-do rear luggage floor panel insulation padding.

\$ 380.00 X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To repair and realign rear exhaust pipe.

\$ 350.00 X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 300

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd

AAD2005-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 620J

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	440
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	60
To Check Electrical Lighting Concerned.	\$	170.00	15
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60
TOTAL	\$	18,660.00	
Over All Total	\$	32,673.57	

(LUMP SUM) Repair Days

25 DAYS

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: