

Not Auth'd
L1 Pump @ 1200/2

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

AAD2005-069

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

29 MAY 2020

SHD 9922P

VF1ABL15AUC277511

RENAULT

LATITUDE

28.5.2020

AIG

5/6/2014

PART		LIST	
1	BUMPER COVER FRT	\$	Sn 747.20
1	BUMPER RETAINER FRT RH	\$	Sn 101.40
1	BUMPER BRACKET FRT RH	\$	n 181.75
1	FENDER PANEL FRT RH	\$	n 437.10
1	WHEELARCH FRT RH	\$	Sn 191.40
1	FENDER BRACKET LOWER RH	\$	Sn 11.80
1	BONNET	\$	n 1,312.70
1	DOOR PANEL FRT RH	\$	n 2,844.66
1	DOOR MIRROR ASSY RH	\$	cin 1,483.40
1	DOOR MIRROR GLASS RH	\$	242.33 X
1	DOOR MIRROR BACK COVER RH	\$	218.46 X
1	DOOR MIRROR LAMP RH	\$	194.18 X
1	DOOR MOULDING FRT RH	\$	Sn 291.27 X
1	ROCKER PANEL OUTER RH	\$	n 1,184.99 X

TOTAL	\$	9,442.64
10%	\$	944.26
	\$	8,498.37

Special Nett

1	BUMPER CLIP FRT	\$	nn 69.00 X
1	BUMPER RETAINER CLIP FRT RH	\$	nn 35.00 X
1	BUMPER BRACKET CLIP FRT RH	\$	nn 25.00 X
1	WHEELARCH CLIP FRT RH	\$	nn 38.00 X
1	FRONT RENAULT TYRE	\$	nn 300.00 X
1	FRONT RENAULT TYRE RIM	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2005-069**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

1 FRONT DOOR STICKER "Trans-Cab"	\$	<i>nn</i>	80.00	<i>x</i>
1 FRONT DOOR STICKER "Classic"	\$	<i>nn</i>	80.00	<i>x</i>
1SET ROCKER PANEL CLIP	\$	<i>nn</i>	40.00	<i>x</i>
TOTAL	\$		1,047.00	

TOTAL PARTS \$ 9,545.37**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *800*

Putty and spray painting of the affected portion.

\$ 6,000.00 *500*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *x*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *h* 380.00 *x*

To transfer of front fender fittings, attachment and perform water seepage test.

\$ *h* 170.00 *x*

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ *h* 170.00 *x*

To transfer of front bumper fittings, attachment and perform water seepage test.

\$ *h* 170.00 *x*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *h* 380.00 *x*

To transfer of door fittings, attachment and perform water seepage test.

\$ *h* 170.00 *x*

Trans-cab Auto Services Pte Ltd

AAD2005-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9922P

To rust-proofing of the affected areas.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,715.37	

LUMP SUM (REPAIR DAY)~~20 DAYS~~*1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: