

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

DATE 28.05.20

TO : MOTOR CLAIMS DEPTS
VEHICLE NO : SMR4525C
MODEL : MERCEDES BENZ GLC250
DATE OF ACCIDENT : 28.05.20
TIME OF ACCIDENT : 18:20HRS

TP AIG

Khanhwa

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER (UPPER) <i>Del'd</i>	1	\$ 2,196.00	\$ 2,196.00
2	FRONT BUMPER (LOWER) <i>Del'd</i>	1	\$ 856.00	\$ 856.00
3	FRONT BUMPER FOGLAMP GARNISH RH <i>new</i>	1	\$ 95.00	\$ 95.00
4	FRONT BUMPER LOWER GRILLE (CENTER CHROME) <i>new</i>	1	\$ 396.00	\$ 396.00
5	FRONT BUMPER LOWER GRILLE (SIDE CHROME) <i>could</i>	2	\$ 151.00	\$ 302.00
6	FRONT BUMPER SENSOR RH <i>could 1 piece</i>	3	\$ 220.00	\$ 660.00
7	FRONT BUMPER SENSOR HOLDER <i>new</i>	6	\$ 65.00	\$ 390.00
8	FRONT BUMPER SIDE RETAINER <i>new Rlt</i>	2	\$ 148.00	\$ 296.00
9	FRONT BUMPER SIDE BRACKET <i>3 piece</i>	2	\$ 80.00	\$ 160.00
10	FRONT BUMPER REINFORCEMENT	1	\$ 504.00	\$ 504.00
11	FRONT BUMPER SPONGE <i>could</i>	1	\$ 198.00	\$ 198.00
12	HEAD LAMP RH <i>could</i>	1	\$ 3,528.00	\$ 3,528.00
13	HEAD LAMP LOWER BRACKET RH <i>2 piece</i>	1	\$ 98.00	\$ 98.00
14	HEAD LAMP SIDE BRACKET RH <i>new</i>	1	\$ 85.00	\$ 85.00
15	FRONT FENDER RH <i>Repair</i>	1	\$ 1,026.00	\$ 1,026.00
16	FRONT FENDER ARCED GARNISH RH <i>cut</i>	1	\$ 277.00	\$ 277.00
17	FRONT FENDER COWLING RH (FRONT) <i>2 piece</i>	1	\$ 213.00	\$ 213.00
18	FRONT FENDER COWLING RH (REAR) <i>new</i>	1	\$ 156.00	\$ 156.00
19	FRONT WHEEL RIM <i>cut - RH</i>	2	\$ 2,394.00	\$ 4,788.00
20	FRONT ABS SENSOR	2	\$ 285.00	\$ 570.00
21	FRONT STEERING RACK & PINION	1	\$ 9,324.00	\$ 9,324.00
22	FRONT WHEEL HUP WITH BEARING	2	\$ 702.00	\$ 1,404.00
23	FRONT SHOCK ABSORBER <i>new</i>	2	\$ 1,062.00	\$ 2,124.00
24	FRONT KNUCKLE ARM <i>new</i>	2	\$ 1,440.00	\$ 2,880.00
25	FRONT CASTER ARM	2	\$ 954.00	\$ 1,908.00
26	FRONT LOWER ARM	2	\$ 828.00	\$ 1,656.00
27	FRONT UPPER ARM	2	\$ 943.00	\$ 1,886.00
28	FRONT STABILIZER LINKAGE	2	\$ 183.00	\$ 366.00
29	REAR BUMPER TOP COVER CHROME	1	\$ 376.00	\$ 376.00
30	REAR BUMPER (UPPER)	1	\$ 1,008.00	\$ 1,008.00

✓

+

✓

220

✓

148

+

+

✓

✓

+

+

+

✓

+

+

2394

+

+

+

+

+

+

+

+

+

TO : MOTOR CLAIMS DEPTS
 VEHICLE NO : SMR4525C
 MODEL : MERCEDES BENZ GLC250
 DATE OF ACCIDENT : 28.05.20
 TIME OF ACCIDENT : 18:20HRS

31	REAR BUMPER (LOWER)	1	\$ 727.00	\$ 727.00	X
32	REAR BUMPER CHROME (CENTER)	1	\$ 496.00	\$ 496.00	X
33	REAR BUMPER REFLECTOR	2	\$ 55.00	\$ 110.00	X
34	REAR BUMPER TOWING COVER	1	\$ 62.00	\$ 62.00	X
35	REAR BUMPER EXHAUST CHROME	2	\$ 397.00	\$ 794.00	X
36	REAR BUMPER EXHAUST CHROME BRACKET	2	\$ 153.00	\$ 306.00	X
37	REAR BUMPER SENSOR	4	\$ 219.00	\$ 876.00	X
38	REAR BUMPER SENSOR HOLDER	6	\$ 68.00	\$ 408.00	X
39	REAR BUMPER SENSOR WIREHARNES	1	\$ 896.00	\$ 896.00	X
40	REAR BUMPER SIDE RETAINER	2	\$ 155.00	\$ 310.00	X
41	REAR BUMPER CENTER TOP BEAM	2	\$ 168.00	\$ 336.00	X
42	REAR BUMPER CENTER LOWER BEAM	1	\$ 269.00	\$ 269.00	X
43	REAR BUMPER LOWER BRACKET	2	\$ 75.00	\$ 150.00	X
44	REAR BUMPER REINFORCEMENT	1	\$ 799.00	\$ 799.00	X
45	TAILLAMP	2	\$ 568.00	\$ 1,136.00	X
46	TAILLAMP LOWER BRACKET	2	\$ 152.00	\$ 304.00	X
47	REAR FENDER COWLING	2	\$ 197.00	\$ 394.00	X
48	REAR WHEEL ARCED GARNISH	2	\$ 278.00	\$ 556.00	X
49	TAILGATE	1	\$ 2,522.00	\$ 2,522.00	X
50	TAILGATE LOGO	1	\$ 84.00	\$ 84.00	X
51	TAILGATE EMBLEM 'GLC'	1	\$ 96.00	\$ 96.00	X
52	TAILGATE EMBLEM '250'	1	\$ 94.00	\$ 94.00	X
53	TAILGATE EMBLEM '4MATIC'	1	\$ 125.00	\$ 125.00	X
54	TAILGATE LOCK	1	\$ 435.00	\$ 435.00	X
55	TAILGATE FOOT SENSOR MODULE	1	\$ 687.00	\$ 687.00	X
56	TAILGATE WEATHER STRIP	1	\$ 383.00	\$ 383.00	X
57	REAR END PANEL	1	\$ 1,372.00	\$ 1,372.00	X
58	REAR END PANEL INNER GARNISH	1	\$ 389.00	\$ 389.00	X
59	REAR FLOOR TOP COVER BOARD	1	\$ 1,203.00	\$ 1,203.00	X
60	REAR EXHAUST BOX	1	\$ 2,192.00	\$ 2,192.00	X
61	REAR EXHAUST INSULATOR	2	\$ 269.00	\$ 538.00	X
62	REAR EXHAUST MOUNTING	4	\$ 42.00	\$ 168.00	X

16509
 9458-10

TOTAL PRICE \$ 58,943.00
 LESS 10% \$ 5,894.30
SUB TOTAL PRICE \$ 53,048.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET)	1	\$ 120.00	\$ 120.00
2	FRONT BUMPER FOGLAMP GARNISH CLIP LH (SET)	1	\$ 40.00	\$ 40.00

30
 4

TO : MOTOR CLAIMS DEPTS
 VEHICLE NO : SMR4525C
 MODEL : MERCEDES BENZ GLC250
 DATE OF ACCIDENT : 28.05.20
 TIME OF ACCIDENT : 18:20HRS

3	FRONT BUMPER BOTTOM GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00	x
4	FRONT FENDER COWLING CLIPS(SET)	1	\$ 80.00	\$ 80.00	x
5	FRONT FENDER ARCED GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00	30
6	FRONT WHEEL TYRE	2	\$ 680.00	\$ 1,360.00	+
7	REAR NUMBER PALTE (SPECIAL TYPE)	1	\$ 180.00	\$ 180.00	x
8	REAR BUMPER CLIP (SET)	1	\$ 120.00	\$ 120.00	x
9	TAILLAMP CLIPS (SET)	1	\$ 50.00	\$ 50.00	x
10	REAR FENDER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00	x
11	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 60.00	\$ 60.00	x
12	REAR WHEEL ARCED GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	+
13	TAILGATE SEALANT	1	\$ 150.00	\$ 150.00	x
14	TAILGATE WINDSCREEN GLASS SEALANT	1	\$ 120.00	\$ 120.00	x
15	TAILGATE WINDSCREEN GLASS INNER SEAL	1	\$ 80.00	\$ 80.00	x
16	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	x
17	REAR END PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00	x

TOTAL \$ 2,950.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	250
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	250
3	WIRING CHECK	\$ 150.00	30
4	REFOCUS HEADLAMP BEAM	\$ 60.00	x
5	REMOVE AND REPLACE FRONT BUMPER SENSOR	\$ 120.00	60
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	+
7	TO PRESS FRONT WHEEL BEARING	\$ 120.00	+
8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	RESET ABS LIGHT	\$ 480.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 650.00	120

TO : MOTOR CLAIMS DEPTS
VEHICLE NO : SMR4525C
MODEL : MERCEDES BENZ GLC250
DATE OF ACCIDENT : 28.05.20
TIME OF ACCIDENT : 18:20HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	2
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	
3	TUFF COAT	\$ 350.00	
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	
5	CONDUCT WATER LEAKAGE TEST	\$ 180.00	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	
7	REMOVE AND REFIX AND RESET VIDEO RECORDER	\$ 80.00	
8	REMOVE AND REFIX AND RESET TAILGATE FOOT SENSOR	\$ 180.00	
9	REMOVE AND REFIX RAILGATE WINDSCREEN GLASS	\$ 120.00	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 250.00	
11	REAR CHASSIS ALIGNMENT	\$ 250.00	

TOTAL \$10,990.00

790

TOTAL PARTS COST : \$ 55,998.70
TOTAL LABOUR COST : \$ 10,990.00
TOTAL REPAIR COST : \$ 66,988.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Abdulla
H/S 01/06/20
03 days .
Total 11030810
L/S: 82K