

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20006043/KEA3Q2
Date: 30/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKM6589E	Insured Vehicle No :	GBJ7373B
Date of Loss:	23/05/2020	Nature of Claim:	TP
		Claim No:	8440664514SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM6589E	Engine No:	3ZRB323712
Make & Model:	TOYOTA RAV4, 2.0 PREMIUM (A)	Chassis No:	JTMDE3EV70D045907
Reg. Date:	27/03/2014 (Man. Year: 2014)	Odometer:	102395 km
Colour:	Metallic Blue		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/05/2020

Date Inspected: 01/06/2020 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$65,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	0.00 F	*- F
2	1		*FRONT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRONT BUMPER BRACKET RH	*Check	0.00 F	*- F
4	1		*FRONT BUMPER SPONGE	*Check	0.00 F	*- F
5	1		*FRONT BUMPER BEAM	*Check	0.00 F	*- F
6	1		*FRONT BUMPER REINFORCEMENT	*Check	0.00 F	*- F
7	1		*FRONT BUMPER TOP RETAINER	*Check	0.00 F	*- F
8	1		*FRONT BUMPER CORE (PLATIC)	*Check	0.00 F	*- F
9	1		*FRONT BUMPER CORNER HOLDER RH	Distorted	0.00 F	*- F
10	1		*FRONT BUMPER FOG LAMP RH	Scratched	0.00 F	*- F
11	1		*FRONT BUMPER FOG LAMP BRACKET RH	*Check	0.00 F	*- F
12	1		*FRONT BUMPER CENTER COVER	Dented / Cut	0.00 F	*- F
13	1		*FRONT BUMPER AIR GRILLE	Serviceable	0.00 F	*- F
14	1		*FRONT BUMPER LOWER AIR GRILLE	Dented	0.00 F	*- F
15	1		*FRONT BUMPER LOWER BEAM	*Check	0.00 F	*- F
16	1		*FRONT BUMPER EMBLEM	Necessary	0.00 F	*- F
17	1		*FRONT BUMPER LOWER LIP	Dented / Cut	0.00 F	*- F
18	1		*FRONT BUMPER LOWER LIP CHROME MOULDING	Dented	0.00 F	*- F
19	1		*FRONT BUMPER SIDE PROTECTOR RH	Distorted	0.00 F	*- F
20	1		*FRONT BUMPER TOW COVER	Cut	0.00 F	*- F
21	1		*FRONT BUMPER RUBBER SEAL	Necessary	0.00 F	*- F
22	1		*FRONT GRILLE RH	Mtg Cracked	0.00 F	*- F
23	1		*FRONT GRILLE CHROME MOULDING	Necessary	0.00 F	*- F
24	1		*HEADLAMP RH (HID)	Cracked	0.00 F	*- F
25	1		*HEADLAMP PANEL RH	Repair	0.00 F	*- F
26	1		*AIRCON CONDENSER	Serviceable	0.00 F	*- F
27	1		*AIRCON CONDENSER AIR GUIDE RH	Serviceable	0.00 F	*- F
28	1		*WIPER TANK	Dented	0.00 F	*- F
29	1		*WIPER TANK MOTOR	Serviceable	0.00 F	*- F
30	1		*FRONT FENDER SHIELD RH	*Check	0.00 F	*- F
31	10		*FRONT FENDER SHIELD CLIPS	*Check	0.00 F	*- F
32	1		*LICENSE PLATE	Dented	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >