

Not Authored
Resony B4 paint

Trans-cab Auto Services Pte Ltd

AAD2005-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5271K

Vehicle No.:

SHD 5271K

Chassis No.:

JTDKB3FU003079117

Vehicle Make:

28 MAY 2020

TOYOTA

Vehicle Model:

PRIUS

Date of Accident :

27.5.2020

Third Party Insurer :

LONPAC

Date of Registration :

25/1/2019

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$ K 1,300.70 X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$ K 97.50 X
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$ K 110.60 X
1 CHECK ASSY, FRONT DOOR	\$ Sn 183.80 X
1 WEATHERSTRIP, FRONT DOOR, LH	\$ Sn 231.30 X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$ na 13.30 X
1 TAPE, BLACK OUT, NO.2 FRT LH	\$ na 43.50 X
1 TAPE, BLACK OUT, NO.3 FRT LH	\$ na 26.30 X
1 LEFT SIDE VIEW MIRROR	\$ CM 1,339.30 ✓
1 COVER, OUTER MIRROR, LH	\$ Sn 108.60 X
1 MIRROR OUTER, LH	\$ K 148.70 X
1 DOOR HARNESS WIRE LH	\$ Sn 532.80 X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ Sn 594.80 X
1 FRONT BUMPER	\$ Sn 516.00 X
1 FRONT BUMPER SIDE RETAINER LH	\$ Sn 82.30 X
1 FRONT BONNET	\$ K 983.10 X
1 FRONT LED LAMP (LOWER) LH	\$ Sn 951.40 X
1 FRONT HEADLAMP LH	\$ Sn 2,637.60 X
1 FRONT FENDER LH	\$ K 977.80 X
1 LINER, FRONT FENDER, LH	\$ Sn 206.70 X
1 FRONT FENDER EMBLEM LH	\$ na 54.60 ✓
TOTAL	\$ 11,140.70
25%	\$ 2,785.18
	\$ 8,355.53

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5271K**AAD2005-061**

1 FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>na</i>	100.00	<i>6000</i>
1 FRONT WHEEL RIM	\$	<i>sm</i>	1,879.40	X
1 FRONT WHEEL RIM COVER	\$	<i>sm</i>	211.50	X
1 FRONT TYRE 195/65/15	\$	<i>sm</i>	350.00	X
1SET FRONT BUMPER RETAINER CLIP	\$	<i>na</i>	39.00	X
1SET FRONT FENDER LINER CLIP	\$	<i>na</i>	38.00	X
1SET FRONT BUMPER CLIP	\$	<i>na</i>	69.00	X
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i>	45.00	X
TOTAL	\$		2,731.90	
TOTAL PARTS	\$		11,087.43	

LABOUR

To transfer of door fittings, attachment and perform water seepage test.	\$		170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>3500</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>Foot</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2005-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5271K

To Check Electrical Lighting Concerned.	\$	170.00	202
To transfer of front bumper fittings, attachment to facilitate bodywork repair.	\$	~ 170.00	X
To transfer of front fender fittings, attachment to facilitate bodywork repair.	\$	~ 170.00	X
To transfer of front bonnet fittings, attachment to facilitate bodywork repair.	\$	~ 170.00	X
TOTAL	\$	14,170.00	
Over All Total	\$	25,257.43	

(PART-BY-PART) Repair Days 20 days
2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: