



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006637
INV Date 25/09/2020
Reference CC3/CTI20006047/Fps3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 6299E
Insured Veh. GBC 6714U
Claim No. SNM20D202017
Policy No. DMCVSNW00026812002
Accident Date 27/05/2020
Inspection Date 28/05/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20006047/Fps3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 6714U	Veh. Inspected	SHC 6299E
Policy No.	DMCVSNW00026812002	Coverage (\$)	0.00
Claim No.	SNM20D202017	Excess (\$)	0.00
Assign From		Assign Date	28/05/2020

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414MF5555006	Colour	SILVER
Odometer	519726	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	8 mm
L/H Rear Tyre	205/65 R16	MAXXIS	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/05/2020	Inspection Date	28/05/2020
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6299E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR O/S TAIL LAMP	NOT NECESSARY	421.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	NOT NECESSARY	58.00	-
1	REAR BUMPER INNER SPONGE	NOT NECESSARY	114.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	607.00	-
2	REAR BUMPER STAY O/S & N/S	NOT NECESSARY	53.00	-
1	REAR BUMPER REINFORCEMENT LOWER BRACKET	NOT NECESSARY	18.00	-
1	REAR BUMPER REINFORCEMENT UPPER BRACKET	NOT NECESSARY	18.00	-
1	REAR BUMPER O/S REFLECTOR	SERVICEABLE	46.00	-
	LESS 10% DISCOUNT		-223.70	-
			2,013.30	-
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			378.00	-
<u>LABOUR</u>				
	TOWING FEE.	NOT NECESSARY	50.00	-
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	60.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	270.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR BUMPER LOWER COVER.		400.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,290.00	510.00

Report Ref No. CC3/CTI20006047/Fps3q2



GRAND TOTAL		3,681.30	510.00
RECOMMENDED COST OF REPAIRS			510.00

Report Ref No. CC3/CTI20006047/Fps3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 6299E

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 6299E

RE-INSPECTION

