

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

28-May-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6299 E

1 pc	Rear o/s tail lamp <i>xm</i>	\$	421.00
1 pc	Rear bumper <i>x(R)</i>	\$	696.00
1 pc	Rear bumper lower cover <i>xm</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>1xm</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>xm</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>xm</i>	\$	607.00
1 pc	Rear bumper stay o/s & n/s @ \$53.00 <i>xm</i>	\$	53.00
1 pc	Rear bumper reinforcement lower bracket @ \$18.00 <i>1xm</i>	\$	18.00
1 pc	Rear bumper reinforcement upper bracket @ \$18.00 <i>1xm</i>	\$	18.00
1 pc	Rear bumper o/s reflector <i>x (sc)</i>	\$	46.00
		\$	2,237.00

Less 10%

\$ 223.70

\$ 2,013.30

S/NETT

1 set	Rear bumper clips <i>xm</i>	\$	48.00
1 set	Reverse sensor <i>xm</i>	\$	280.00
	Sundry	\$	50.00 <i>xm</i>
	Towing Fee	\$	50.00 <i>1</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 <i>\$60</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	600.00 <i>\$270</i>
	To putty and spray painting on rear bumper, rear bumper lower cover	\$	400.00 <i>\$180</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 <i>xm</i>
		\$	3,681.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

P/P Repair

2550/2

2nd day

Ram (LKK)

28/05/2020 # 1130

88622778

AA repair plate