PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

28-May-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6299 E

1 pc	Rear o/s tail lamp × ^ ^		\$	421.00
1 pc	Rear bumper ×(R)		\$	696.00
1 pc	Rear bumper lower cover ⋉∧⋌		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 $ \gamma$		\$	58.00
1 pc	Rear bumper inner sponge		\$	114.00
1 pc	Rear bumper reinforcement $\times \sim$		\$	607.00
1 pc	Rear bumper stay o/s & n/s @ \$53.00 ★ ∧ ∧		\$	53.00
1 pc	Rear bumper reinforcement lower bracket @ \$18.00		\$	18.00
1 pc	Rear bumper reinforcement upper bracket @ \$18.00		\$	18.00
1 pc	Rear bumper o/s reflectors		\$	46.00
			\$	2,237.00
		Less 10%	\$:	223.70
S/NETT		LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting	\$	2,013.30
1 set	Rear bumper clips	 To display damaged part(s) during resurvey Parts prices are subject to confirmation 	\$	48.00
1 set	Reverse sensor	Third party survey is on a "Without Prejudice" basis	\$	280.00
1 561	Neverse sensor XVV	 No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and 	Ψ	280.00
	Sundry	is subject to final approval from Insurance Company	\$	50.00 ×n∽
	Towing Fee	Acknowledged by Repairer Signature:	\$	50.00 7
		Date:	Ψ	30.00
	To dismantle / replace reverse serisor to new bumper and reset to the same		\$	120.00\$60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	600.00\$270
*	To putty and spray painting on rear bumper, rear bumper lower cover		\$	400.00\$ 180
	To apply rustproofing on the repaired and replaced panels.		\$	120.00&×vn
			\$	3,681.30
			\	10 to 2

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.