

Survivor

Steve

REF:

CS/MSG20906049/ETf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP-RES/OD-RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured.

Policy No.

Claims No.


Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh. had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PP. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

MIV-6SK

lumpsum \$4500, 4days (red: 7316.30,61%)

Date/Time, File Plss to?

☐

: Proll. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 4500 lump sum)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

: \$ + RS. - SI

: P/B

: Q/B

: ..

TOTAL

Veh No:

SML 521X

Yr Regn:

2/5/19

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

c.c

1591

Colour

Gy

A/C:

Insured / Std / Nil / NA

Sp.Reading

16847

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

KMH0841CMK 881468

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: ☒ Nil / ☐ STD / ☐ STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/5/20

D.O.I.

1/6/20

Survey held at

Auburn Arb

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Frt LH

The UIC / Chassis frame / Body Structure affected due to collision.

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: auburnauto.claim@gmail.com

Vehicle No: SML521X

Model: Hyundai Avante

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bumper side grille (LH) / CUT \$	180.00 92-60 /
2 /	Front bonnet L/H & R/H fog lamp cover (LH) / CUT \$	440.00 115-40 /
1	Front bonnet lock Bumper lower spoiler / CUT \$	380.00 265-20 /
1	Front bonnet inner rubber X N/A \$	68.20 X
1	Front bonnet outer rubber X N/A \$	86.20 X
1	Front bumper inner sponge X N/A \$	135.90 X
1 2	Front bumper side retainers / DR \$	145.20 /
1	Front fender inner shield (LH) / CRU \$	426.50 265 /
1	Front headlamp lower bracket / DR (LH) \$	186.00 98-20 /
1	Front grille chrome moulding Bumper fog lamp LH / CUT \$	285.90 165-80 /
1	Front grille logo / NR \$	188.80 71 /
1	Front grille / DR \$	628.60 /
1	Front Bumper / DR \$	1,250.00 785-80 /
1	Front bonnet lock X N/A \$	380.00 X
2	L/H and R/H Mud Flap X N/A \$	160.00 X
2 /	L/H Headlight (LH) / DR (HID type) \$	1,500.00 /
1	Bonnet Front LH Rim / CUT \$	950.00 600 /
1	Front L/H Fender / DR \$	660.00 /
1	Car Plate and Carplate Holder X N/A \$	190.00 X
1	Chrome "Hyundai" logo X N/A \$	135.00 X

\$ 8,376.30

c/f: \$ \$ 8,376.30

	Special Nett Items	AMT S\$
1	Rear Windscreen Sealant X /M/	\$ 120.00
1	Front bumper clip / M	\$ 150.00 J
		<u>\$ 270.00</u>

S/N. **Labour Charges**

Remove and refit Front Bumper	\$	300.00	200
Remove, refit and replaced damage lamps and check up rear electrical wiring	\$	150.00	30
Remove and refit inner garnishes trim to assist repair	\$	200.00	50
To apply undercoating on replaced panel	\$	120.00	30
To Respray Painting.	\$	1,200.00	600
Panel Beating	\$	1,200.00	400
	\$	<u>3,170.00</u>	
GRAND TOTAL	<u>\$</u>	<u>11,816.30</u>	

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 83228813
(Email) _____
(Signature) 
(Date/Time) 1/6/20, 2.30pm

WU R
4 wgs
L/S
My L by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: