

K9

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	020053
Policy No:	MPC20P00007300	Date of Loss:	28/05/2020
Vehicle Reg. No.:	SLS4483X	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
P Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	HARVINDER SINGH S/O KUSHVINDER SINGH	Contact No:	+6598794930
Driver:	HARVINDER SINGH S/O KUSHVINDER SINGH		
Make/Model:	MITSUBISHI LANCER, 1.6 (M)	Vehicle Reg. Date:	30/01/2008
Vehicle Colour:	BLACK		
Engine No:	4G18JN6383	Chassis No:	JMYSNCS3A8U003067
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7 ✓		
Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)		

*Not Authorized
11 Rmp & 4850h
Running After Repair*

COST OF CLAIMS	Amount
Parts	4,540.50
Miscellaneous Items	0.00
Labour	2,110.00
Paintwork Labour	0.00
Polishing	0.00
Gross Total (S\$)	6,650.50
+ GST 7.00% (S\$)	465.54
Nett Amount (S\$)	7,116.04

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2020)
 ts: 143 MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)
 our: Repairer's (Price-denominated Standard List)
 nt Code: Alan's United Auto Pte Ltd/SLS4483X/30/05/2020 11:00
 idity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 ther Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1		*BOOT LID	B ₁ 0.00	0.00	*380.00 F	✓
1		*BOOT LID LANCER EMBLEM	M ₁ 0.00	0.00	*24.00 F	✓
1		*BOOT LID INNER LOCK		0.00	R *65.00 F	X
1		*BOOT LID RUBBER	Pis/M ₁ 0.00	0.00	*95.00 F	✓
2		*BOOT LID HINGE	B ₁ 0.00	0.00	*170.00 F	✓
2		*TAILLAMP	B ₁ 0.00	0.00	*490.00 F	✓
4		*TAILLAMP SIDE CLIP	M ₁ 0.00	0.00	*20.00 F	✓
1		*REAR END PANEL	B ₁ 0.00	0.00	*280.00 F	✓
1		*REAR END PANEL TOP GARNISH	S ₁ 0.00	0.00	*109.00 F	X
1		*REAR LH FENDER	B ₁ 0.00	0.00	*480.00 F	✓
1		*REAR LH FENDER AIR DUCT	M ₁ 0.00	0.00	*20.00 F	✓
1		*REAR LH FENDER INNER SHIELD	C ₁ 0.00	0.00	*18.00 F	✓
1		*REAR LH FENDER INNER TRIM COVER	D ₁ 0.00	0.00	*95.00 F	✓
1		*REAR W/S GLASS TOP MOULDING	M ₁ 0.00	0.00	*24.00 F	✓
1		*REAR LH CHASSIS MEMBER EXTENSION	B ₁ 0.00	0.00	*155.00 F	✓
1		*SPARE TYRE PANEL	M1/B ₁ 0.00	0.00	*680.00 F	✓
1		*SPARE TYRE PANEL BOARD	S ₁ 0.00	0.00	*95.00 F	X
1		*REAR BUMPER FASCIA	B ₁ 0.00	0.00	*420.00 F	✓
2		*REAR BUMPER SIDE BEAM	D ₁ 0.00	0.00	*72.00 F	✓
1		*REAR BUMPER CENTRE BEAM	B ₁ 0.00	0.00	*65.00 F	✓
12		*REAR BUMPER SIDE BEAM RIVET	M ₁ 0.00	0.00	*18.00 F	✓
1		*FRONT LH LOWER ARM	D ₁ C ₁ 0.00	0.00	*180.00 F	✓
1		*REAR BUMPER REVERSE SENSOR (SET)	T ₁ 0	0.00	*150.00 FS	✓
1		*REAR W/S GLASS SEALANT	M ₁ 0	0.00	*40.00 FS	✓

anchise part. S=SpcNett.

Sub Total (S\$) 4,145.00
 + Margin on L,N Items 10.00% (S\$) 395.50

Total Parts (S\$) 4,540.50

Alan's United Auto Pte Ltd/SLS4483X/30/05/2020 11:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TOWING FEE	New	40.00
2	TO REMOVE & REFIX REAR W/S GLASS AND CONDUCT WATER LEAK TEST	New	120.00
3	TO REMOVE ROOF LINING , REAR SEAT ,TRIM BOARD AND CARPET	New	100.00
4	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	80.00
5	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	50.00
6	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00
7	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	800.00
8	TO REPAIR FRONT LH SPORT RIM	New	120.00
Gross Labour Cost (S\$)			2,110.00

Alan's United Auto Pte Ltd/SLS4483X/30/05/2020 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: