



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 1234E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR L/H TOP BOX PANEL (SN) }	DENTED	3,000.00	1,600.00
1	REAR L/H CENTER BOX PANEL (SN) }		4,000.00	-
1	REAR L/H BOX LOWER PANEL (SN) }		4,000.00	-
1	REAR L/H BOX PANEL STICKER (SN)	NECESSARY	1,150.00	600.00
1	REAR L/H BOX PANEL FRAME (SN)	DENTED	2,500.00	1,200.00
1	REAR TOP RAIN CHANNEL (SN)	DISTORTED	800.00	300.00
1	REAR LOWER HORIZONTAL WOODEN PLANK (SN)	CRACKED	1,000.00	480.00
1	REAR LOWER ALUMINIUM COVER (SN)	NOT NECESSARY	650.00	-
1	REAR TAILGATE BUMPER RUBBER (SN)	NOT NECESSARY	80.00	-
1	REAR L/H TAILGATE STOPPER RUBBER (SN)	NOT NECESSARY	50.00	-
1	REAR L/H TAILGATE (SN)	DENTED	3,500.00	1,800.00
3	REAR L/H TAILGATE TOP, CENTER & LOWER HINGE @\$350.00 (SN)	BENT	1,050.00	600.00
1	REAR L/H TAILGATE INNER PLYWOOD (SN)	NOT NECESSARY	650.00	-
1	REAR L/H TAILGATE INNER STAINLESS STEEL COVER (SN)	NOT NECESSARY	1,500.00	-
5	REAR L/H TAILGATE STICKER (SN)	NECESSARY	850.00	500.00
			24,780.00	7,080.00
<b><u>LABOUR</u></b>				
	TO REMOVE & REFIT REAR CONTAINER BOX.		3,000.00	600.00
	TO REMOVE & REFIT REAR WOODEN CHASSIS MEMBER.		800.00	100.00
	TUFF KOTE.		200.00	200.00
	PANEL BEATING.		1,500.00	600.00
	SPRAY PAINTING.		2,500.00	800.00
			-	-
			-	-
			8,000.00	2,300.00
<b>GRAND TOTAL</b>			<b>32,780.00</b>	<b>9,380.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,500.00</b>

Report Ref No. CS/SMO20006053/Ayf3e2



Report Ref No. CS/SMO20006053/Ayf3e2

A handwritten signature in black ink, appearing to read 'A. Ling'.

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**