



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20006053/Ayf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-07-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 6706C	Veh. Inspected	YP 1234E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001691	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	01/06/2020

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FM65FMA20071	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	11 R22.50	BRIDGESTONE	6 mm
L/H Front Tyre	11 R22.50	BRIDGESTONE	6 mm
R/H Rear Tyre	11 R22.50	BRIDGESTONE	6 mm
L/H Rear Tyre	11 R22.50	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2020	Inspection Date	04/06/2020
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
--	-----------------------