

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

04/06/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Sompō

Jronne

Accident date: 29/05/2020

Estimated repair cost for vehicle no: YP1234E MITSUBISHI FUSO FM65FM2RDEB

CHASSIS: FM65FMA20071

7.5 M '16

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Rear L/H Top Box Panel		\$3,000.00
2	1	Rear L/H Center Box Panel		\$4,000.00
3	1	Rear L/H Box Lower Panel		\$4,000.00
4	1	Rear L/H Box Panel Sticker		\$1,150.00
5	1	Rear L/H Box Panel Frame		\$2,500.00
6	1	Rear Top Rain Channel		\$800.00
7	1	Rear Lower Horizontal Wooden Plank		\$1,000.00
8	1	Rear Lower Aluminium Cover		\$650.00
9	1	Rear Tailgate Bumper Rubber		\$80.00
10	1	Rear L/H Tailgate Stopper Rubber		\$50.00
11	1	Rear L/H Tailgate		\$3,500.00
12	3	Rear L/H Tailgate Top, Center & Lower Hinge	\$350.00	\$1,050.00
13	1	Rear L/H Tailgate Inner Plywood		\$650.00
14	1	Rear L/H Tailgate Inner Stainless Steel Cover		\$1,500.00
15	5	Rear L/H Tailgate Sticker		\$850.00

Subtotal :- \$24,780.00

7080

Labour charges

To remove & refit rear container box		\$3,000.00 600
To remove & refit rear wooden chassis member		\$800.00 100
Tuff kote		\$200.00 200
Panel beating	2300	\$1,500.00 600
Spray painting		\$2,500.00 800
Subtotal :-		<u>\$8,000.00</u>
Total:-		<u>\$32,780.00</u>

total: 9380

4/5 7.5K

06 Days

(7.5K)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:.