



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20003581/Etf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-06-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7773G	Veh. Inspected	SJN 2261H
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20030043	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	01/06/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GE61130600	Colour	WHITE
Odometer	356188	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	6 mm
L/H Front Tyre	195/55 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	FALKEN	5 mm
L/H Rear Tyre	185/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/03/2020	Inspection Date	04/03/2020
Survey held at	8 KAKI BUKIT AVE 4 #04-20 PREMIER		
Repairer	A-TEC AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------