RALLY PITSTOP

176 Sin Ming Drive #04-17 Sin Ming Autocare Singapore 575721 Tel: 64516985

Email: tar6985@hotmail.com • Parts prices are subject to confirmation

Your Insured: S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: 9396D Date:

Date:01/06/2020

To: Motor Claims Department **UOI** Insurance

RE: Estimate repair cost of SLC6809L

Dear Sir/Madam, Vehicle No: SLC6809L Make Model: Mazda / 5 Date of accident: 31/05/2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Bonnet 15th	Jane 1 1100	797.40
1	Bonnet hindge(LH)		93.90
1	Head lamp (LH) Swows		895.30
1	Front bumper Redick		649.00
1	Front bumper retainer (LH)		75.00
1	Front reinforcement 2 45		648.90 75.80 545.20
5	Front bumper clips Have	3.00	15.00
1	Fog light (LH) 2. monty work	3.00	189.80
1	Fog light cover(LH) Cut Deady		110.90
1	Front bumper lower spoiler CA		590.20
1	Front bumper logo Leo		88.20
1	Front radiator support panel HA		564.30
1	Front grille when		342.80
1	Front numbers plate		60.00
			00.00
	Sub-total before discount		5017.70
	Parts percentage discount 15% → 30%		752.66
	PARTS TOTAL		4265.04
	LABOUR CHARGES & MISC		
1	Labour to dismantle and change all damaged parts		1000.00
2	To putty and spray paint		800.00
3	To do undercoating		60.00
4	To check wiring		40.00
	LABOUR TOTAL		1900.00
	LABOUR & PARTS TOTAL		6165.04

Regards, Terrence Lim 01/06/2020 e Hoom

N/A ANHAN

L/Sm/ 4 day.