

RALLY PITSTOP

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 64516985
Email: tar6985@hotmail.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Date: 01/06/2020

To: Motor Claims Department
UOI Insurance

RE: Estimate repair cost of SLC6809L

Your Insured: SLJ9396D

Dear Sir/Madam,
Vehicle No: SLC6809L
Make Model: Mazda / 5
Date of accident: 31/05/2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Bonnet <i>BT</i>		797.40
1	Bonnet hinged(LH) <i>HL</i>		93.90
1	Head lamp (LH) <i>Scratched / mainly broken</i>		895.30
1	Front bumper <i>Replaced</i>		648.90
1	Front bumper retainer (LH) <i>HL</i>		75.80
1	Front reinforcement <i>2 BT</i>		545.20
5	Front bumper clips <i>HL</i>	3.00	15.00
1	Fog light (LH) <i>2. mainly cracked</i>		189.80
1	Fog light cover(LH) <i>cut / Replaced</i>		110.90
1	Front bumper lower spoiler <i>cut</i>		590.20
1	Front bumper logo <i>HL</i>		88.20
1	Front radiator support panel <i>HL</i>		564.30
1	Front grille <i>crack / broken</i>		342.80
1	Front numbers plate <i>HL</i>		60.00
	Sub-total before discount		5017.70
	Parts percentage discount 15% <i>20%</i>		752.66
	PARTS TOTAL		4265.04
	LABOUR CHARGES & MISC		
1	Labour to dismantle and change all damaged parts		1000.00
2	To putty and spray paint		800.00
3	To do undercoating		60.00
4	To check wiring		40.00
	LABOUR TOTAL		1900.00
	LABOUR & PARTS TOTAL		6165.04

Regards,
Terrence Lim

01/06/2020 e170m

not Author

1/Smr 4 days

Tuan
LKK And

4538.96

L/S 3600/-