

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 03 Jun 2020

Preliminary Advice

Insured Vehicle No : SMF4323G

TP Vehicle No : FJ33G

Make : HONDA NC750XA

Date of Inspection : 02/06/2020

Inspection At : Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Accident Date : 29/05/2020

Assignment Date : 01/06/2020

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,054.00
Revised Amount	:S\$	2,288.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,288.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP