

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D**AAD2005-071***Not Authorized**Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 JUN 2020**SHD 9354D**

JTDKB3FU803079382

TOYOTA

PRIUS

28.5.2020

FCIL

11/3/2019

	PART
1	REAR BUMPER
1	REAR BUMPER RE-INFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER LH
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	TAILLAMP LOWER LH
1	TAILLAMP UPPER LH
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO 1
1	COVER, FLOOR UNDER, NO 2
1	COVER, REAR FLOOR

	LIST	
\$	Bu	442.60 ✓
\$	R	332.70 X
\$	Sn	15.40 X
\$	Duller	576.30 ✓
\$	Sn	116.50
\$	Sn	117.70
\$	R	1,147.80
\$	Sn	925.60
\$	Sn	372.30 X
\$	Sn	650.30
\$	Sn	502.00
\$	Sn	451.80
\$	Sn	123.70
\$	Sn	123.70
\$	Car	502.00 ✓
\$	Sn	443.30 X
\$	Sn	126.70 X
\$	Sn	175.10 X
\$	Sn	241.90 X
\$	Sn	229.90 X

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

1SET	PARKING AID	\$	Sn	700.00 X
1SET	REAR BUMPER CLIP	\$	Sn	69.00 ✓
1	REAR TAILGATE TOYOTA LOGO	\$	Sn	47.00 X

Trans-cab Auto Services Pte Ltd

AAD2005-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	X
1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	X
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	X
1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	X
1	REAR BUMPER PROTECTOR	\$	nn	120.00	30sm
1	REAR WHEEL RIM	\$	sh	1,879.40	} X
1	REAR TYRE 195/65/15	\$	sh	350.00	
1	REAR WHEEL RIM COVER	\$	sh	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	nn	38.00	
1	REAR LH BUMPER RETAINER CLIP	\$	nn	38.00	
1SET	TAILLAMP LOWER CLIP	\$	nn	33.00	
1SET	TAILLAMP UPPER CLIP	\$	nn	33.00	
1	Rear Licence Plate with Moulding	\$	nn	100.00	
TOTAL		\$		3,885.30	
TOTAL PARTS		\$		9,598.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ 4 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 4 170.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 4 380.00 X

To check steering geometry and computer wheel alignment

\$ 4 220.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 200l

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 280l

Trans-cab Auto Services Pte Ltd**AAD2005-071**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>4</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>202</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,768.28	

(PART-BY-PART) Repair Days**20 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: