

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9354D

AAD2005-071

Not Authorized
Resurvey B4 paint

Vehicle No.:
 Chassis No.:
 Vehicle Make: **01 JUN 2020**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD 9354D
 JTDKB3FU803079382
 TOYOTA
 PRIUS
 28.5.2020
FCIL
 11/3/2019

PART	LIST	
1 REAR BUMPER	\$ Bu	442.60 ✓
1 REAR BUMPER RE-INFORCEMENT	\$ R	332.70 X
1 REAR BUMPER TOWING COVER	\$ Sn	15.40 X
1 GUARD, REAR BUMPER, CENTER	\$ Duller	576.30 ✓
1 REAR BUMPER SIDE RETAINER LH	\$ Sn	116.50
1 REAR BUMPER SIDE RETAINER RH	\$ Sn	117.70
1 REAR TAILGATE	\$ R	1,147.80
1 REAR TAILGATE OUTER GARNISH	\$ Sn	925.60
1 REAR TAILGATE WEATHERSTRIP	\$ Sn	372.30 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ Sn	650.30
1 TAILLAMP LOWER RH	\$ Sn	502.00
1 TAILLAMP UPPER RH	\$ Sn	451.80
1 REAR BUMPER SIDE RH	\$ Sn	123.70
1 REAR BUMPER SIDE LH	\$ Sn	123.70
1 TAILLAMP LOWER LH	\$ Cr	502.00 ✓
1 TAILLAMP UPPER LH	\$ Sn	443.30 X
1 COVER, DECK TRIM, REAR	\$ Sn	126.70 X
1 COVER, FLOOR UNDER, NO 1	\$ Sn	175.10 X
1 COVER, FLOOR UNDER, NO 2	\$ Sn	241.90 X
1 COVER, REAR FLOOR	\$ Sn	229.90 X

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

1SET PARKING AID	\$	Sn 700.00 X
1SET REAR BUMPER CLIP	\$	nc 69.00 ✓
1 REAR TAILGATE TOYOTA LOGO	\$	nn 47.00 X

Trans-cab Auto Services Pte Ltd

AAD2005-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>Nn</i>	52.90	X
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>Nn</i>	53.50	X
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>Nn</i>	80.00	X
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>Nn</i>	80.00	X
1	REAR BUMPER PROTECTOR	\$	<i>Nn</i>	120.00	<i>3000</i>
1	REAR WHEEL RIM	\$	<i>Sh</i>	1,879.40	} X
1	REAR TYRE 195/65/15	\$	<i>Sh</i>	350.00	
1	REAR WHEEL RIM COVER	\$	<i>Sh</i>	211.50	
1	REAR RH BUMPER RETAINER CLIP	\$	<i>Nn</i>	38.00	
1	REAR LH BUMPER RETAINER CLIP	\$	<i>Nn</i>	38.00	
1SET	TAILLAMP LOWER CLIP	\$	<i>Nn</i>	33.00	
1SET	TAILLAMP UPPER CLIP	\$	<i>Nn</i>	33.00	
1	Rear Licence Plate with Moulding	\$	<i>Nn</i>	100.00	
TOTAL		\$		3,885.30	
TOTAL PARTS		\$		9,598.28	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>Nn</i>	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>h</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>h</i>	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>h</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>h</i>	220.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>2000</i>
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>2000</i>

Trans-cab Auto Services Pte Ltd

AAD2005-071

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9354D

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>h</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>h</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>202</i>
TOTAL	\$		14,170.00	
Over All Total	\$		23,768.28	

(PART-BY-PART) Repair Days

20 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: