

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 May 2020 Edit Reg		02 Jun 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: CLARICE LEONG KOON YING , ID: S7613133C									
Main Claimant: CHUA CHWEE SENG									
Vehicle Reg. No.: SJT9911M		Date of Loss: 23/05/2020 07:00 - :59 [124 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7194165598SG		Policy/Cover Note No.: 1800059078 (Comprehensive) Coverage: 05/06/2018 - 04/06/2020							
Vehicle Reg. No. (Insured): SJJ924M		Policy No. (Claimant):							
Excess:									
Repairer: Sk Garage Motorsports - Soon Lee (HQ) 5 SOON LEE STREET, #01-34, 627607 Pioneer - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/06/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (03/06/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJT9911M (7194165598SG)**
[SJJ924M]
TP
CHUA CHWEE SENG
May 23 2020 7:00AM
[CLARICE LEONG KOON YING]
Sk Garage Motorsports - Soon Lee

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser ▾

Video 1 per page ▾ ☒

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/06/20 10:29	Video - Accident		Load MP4	

Photos/Images 3 per page ▾ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/06/20 18:09	General View		Load JPG	☒
2	02/06/20 18:09	General View		Load JPG	☒
3	02/06/20 18:09	General View		Load JPG	☒
4	02/06/20 18:09	General View		Load JPG	☒
5	02/06/20 18:09	General View		Load JPG	☒
6	02/06/20 18:09	General View		Load JPG	☒
7	02/06/20 18:09	General View		Load JPG	☒
8	02/06/20 18:09	General View		Load JPG	☒
9	02/06/20 18:09	General View		Load JPG	☒
10	02/06/20 18:09	General View		Load JPG	☒
11	02/06/20 18:09	General View		Load JPG	☒
12	02/06/20 18:09	General View		Load JPG	☒
13	02/06/20 18:09	General View		Load JPG	☒
14	02/06/20 18:09	General View		Load JPG	☒
15	02/06/20 18:09	General View		Load JPG	☒
16	02/06/20 18:09	General View		Load JPG	☒
17	02/06/20 18:09	General View		Load JPG	☒
18	02/06/20 18:09	General View		Load JPG	☒
19	02/06/20 18:09	General View		Load JPG	☒
20	02/06/20 18:09	General View		Load JPG	☒
21	02/06/20 18:09	General View		Load JPG	☒
22	02/06/20 18:09	General View		Load JPG	☒
23	02/06/20 18:09	General View		Load JPG	☒
24	02/06/20 18:09	General View		Load JPG	☒
25	02/06/20 18:09	General View		Load JPG	☒
26	02/06/20 18:09	General View		Load JPG	☒
27	02/06/20 18:09	General View		Load JPG	☒
28	02/06/20 18:09	Odometer Reading		Load JPG	☒
29	02/06/20 18:09	Chassis Number		Load JPG	☒
30	02/06/20 18:09	General View		Load JPG	☒
31	02/06/20 18:09	General View		Load JPG	☒
32	02/06/20 18:09	General View		Load JPG	☒
33	02/06/20 18:09	General View		Load JPG	☒
34	02/06/20 18:09	General View		Load JPG	☒
35	02/06/20 18:09	General View		Load JPG	☒
36	02/06/20 18:09	General View		Load JPG	☒
37	02/06/20 18:09	General View		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
38	02/06/20 18:09	General View		Load JPG	☒
39	02/06/20 18:09	General View		Load JPG	☒
40	02/06/20 18:09	General View		Load JPG	☒
41	02/06/20 18:09	General View		Load JPG	☒
42	02/06/20 18:09	General View		Load JPG	☒
43	02/06/20 18:09	General View		Load JPG	☒
44	02/06/20 18:09	General View		Load JPG	☒
45	02/06/20 18:09	General View		Load JPG	☒
46	02/06/20 18:09	General View		Load JPG	☒
47	09/06/20 14:31	Reinspection Photo		Load JPG	☒
48	09/06/20 14:31	Reinspection Photo		Load JPG	☒
49	09/06/20 14:31	Reinspection Photo		Load JPG	☒
50	09/06/20 14:31	Reinspection Photo		Load JPG	☒
51	09/06/20 14:31	Reinspection Photo		Load JPG	☒
52	09/06/20 14:31	Reinspection Photo		Load JPG	☒
53	09/06/20 14:31	Reinspection Photo		Load JPG	☒
54	09/06/20 14:31	Reinspection Photo		Load JPG	☒
55	09/06/20 14:31	Reinspection Photo		Load JPG	☒
56	09/06/20 14:31	Reinspection Photo		Load JPG	☒
57	09/06/20 14:31	Reinspection Photo		Load JPG	☒
58	09/06/20 14:33	Reinspection Photo		Load JPG	☒
59	09/06/20 14:33	Reinspection Photo		Load JPG	☒
60	09/06/20 14:33	Reinspection Photo		Load JPG	☒
61	09/06/20 14:33	Reinspection Photo		Load JPG	☒
62	09/06/20 14:33	Reinspection Photo		Load JPG	☒
63	09/06/20 14:33	Reinspection Photo		Load JPG	☒
64	09/06/20 14:33	Reinspection Photo		Load JPG	☒
65	09/06/20 14:33	Reinspection Photo		Load JPG	☒
66	09/06/20 14:33	Reinspection Photo		Load JPG	☒
67	09/06/20 14:33	Reinspection Photo		Load JPG	☒
68	09/06/20 14:33	Reinspection Photo		Load JPG	☒
69	09/06/20 14:33	Reinspection Photo		Load JPG	☒
70	09/06/20 14:33	Reinspection Photo		Load JPG	☒
71	09/06/20 14:33	Reinspection Photo		Load JPG	☒
72	09/06/20 14:33	Reinspection Photo		Load JPG	☒
73	09/06/20 14:33	Reinspection Photo		Load JPG	☒
74	09/06/20 14:33	Reinspection Photo		Load JPG	☒
75	09/06/20 14:33	Reinspection Photo		Load JPG	☒
76	09/06/20 14:33	Reinspection Photo		Load JPG	☒
77	09/06/20 14:33	Reinspection Photo		Load JPG	☒
78	09/06/20 14:33	Reinspection Photo		Load JPG	☒
79	09/06/20 14:33	Reinspection Photo		Load JPG	☒
80	09/06/20 14:33	Reinspection Photo		Load JPG	☒
81	09/06/20 14:33	Reinspection Photo		Load JPG	☒
82	09/06/20 14:33	Reinspection Photo		Load JPG	☒
83	09/06/20 14:33	Reinspection Photo		Load JPG	☒
84	09/06/20 14:33	Reinspection Photo		Load JPG	☒
85	09/06/20 14:33	Reinspection Photo		Load JPG	☒
86	09/06/20 14:33	Reinspection Photo		Load JPG	☒
87	09/06/20 14:33	Reinspection Photo		Load JPG	☒
88	09/06/20 14:33	Reinspection Photo		Load JPG	☒
89	09/06/20 14:33	Reinspection Photo		Load JPG	☒
90	09/06/20 14:33	Reinspection Photo		Load JPG	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
91	09/06/20 14:33	Reinspection Photo		Load JPG	☒
92	09/06/20 14:33	Reinspection Photo		Load JPG	☒
93	09/06/20 14:33	Reinspection Photo		Load JPG	☒
94	09/06/20 14:33	Reinspection Photo		Load JPG	☒
95	09/06/20 14:33	Reinspection Photo		Load JPG	☒
96	09/06/20 14:33	Reinspection Photo		Load JPG	☒
97	09/06/20 14:33	Reinspection Photo		Load JPG	☒
98	09/06/20 14:33	Reinspection Photo		Load JPG	☒
99	09/06/20 14:33	Reinspection Photo		Load JPG	☒
100	09/06/20 14:33	Reinspection Photo		Load JPG	☒
101	09/06/20 14:33	Reinspection Photo		Load JPG	☒
102	09/06/20 14:33	Reinspection Photo		Load JPG	☒
103	09/06/20 14:33	Reinspection Photo		Load JPG	☒
104	09/06/20 14:33	Reinspection Photo		Load JPG	☒
105	09/06/20 14:33	Reinspection Photo		Load JPG	☒
106	09/06/20 14:33	Reinspection Photo		Load JPG	☒
107	09/06/20 14:33	Reinspection Photo		Load JPG	☒
108	09/06/20 14:33	Reinspection Photo		Load JPG	☒
109	09/06/20 14:33	Reinspection Photo		Load JPG	☒
110	09/06/20 14:33	Reinspection Photo		Load JPG	☒
111	09/06/20 14:33	Reinspection Photo		Load JPG	☒
112	09/06/20 14:33	Reinspection Photo		Load JPG	☒
113	09/06/20 14:33	Reinspection Photo		Load JPG	☒
114	09/06/20 14:33	Reinspection Photo		Load JPG	☒
115	09/06/20 14:33	Reinspection Photo		Load JPG	☒
116	09/06/20 14:33	Reinspection Photo		Load JPG	☒
117	09/06/20 14:33	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/06/20 13:00	tp Singapore Accident Statement		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/06/20 10:29	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20006077/T1TF3S2**Date:** 23/06/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800059078
Claimant Vehicle No :	SJT9911M	Insured Vehicle No :	SJJ924M
Date of Loss:	23/05/2020	Nature of Claim:	TP
		Claim No:	7194165598SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9911M		
Make & Model:	MERCEDES-BENZ C200, 1.8 Kompressor (A)	Engine No:	27195031277176
Reg. Date:	15/01/2010 (Man. Year: 2009)	Chassis No:	WDD2040412A332374
Colour:	White	Odometer:	152918 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/06/2020	
Date Inspected:	02/06/2020	Inspected At: Sk Garage Motorsports - Soon Lee (HQ) 5 SOON LEE STREET, #01-34 Singapore 627607
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*FRT BUMPER CHROME MOULDING	Distorted	0.00 F	*- F
5	1		*FRT BUMPER SENSOR	Distorted	0.00 F	*- F
6	1		*FRT BUMPER FOG LAMP RH	Distorted	0.00 F	*- F
7	1		*FRT BUMPER FOG LAMP GARNISH	Distorted	0.00 F	*- F
8	1		*FRT HEADLAMP RH	Cracked	0.00 F	*- F
9	1		*FRT RH FENDER	Bent	0.00 F	*- F
10	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
11	1		*BONNET	Bent	0.00 F	*- F
12	1		*BONNET EMBLEM	Necessary	0.00 F	*- F
13	1		*FRT RH RIM	Cut	0.00 F	*- F
14	1		*FRT RH TYRE	Cut	0.00 F	*- F
15	1		*FRT RH LOWER ARM	Bent	0.00 F	*- F
16	1		*FRT RH KNUCKLE ARM	Bent	0.00 F	*- F
17	1		*FRT RH KNUCKLE ARM BEARING	Bent	0.00 F	*- F
18	1		*FRT RH SHOCK ABSORBER	Bent	0.00 F	*- F
19	1		*RH ROCKER PANEL GARNISH	Deformed	0.00 F	*- F
20	1		*FRT RH DOOR	Repair	0.00 F	*- F
21	1		*FRT RH FENDER MOULDING	Necessary	0.00 F	*- F
22	1		*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
23	1		*FRT RH DOOR MOULDING	Necessary	0.00 F	*- F
24	1		*FRT GRILLE	Distorted	0.00 F	*- F
25	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
26	1		*FRT BUMPER SPONGE	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >