

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **GBT 30655**

Model:

Chassis No:

Year of manufacturing:

S/No	Qty	Items	Unit Price	Amount
1	1	RHS Front Fender / DD	\$ 585.20	\$ 585.20 ✓
2	1	RHS Front Fender Shield X NN	\$ 218.20	\$ 218.20 X
3	1	RHS Front Fender Signal - CNT	\$ 70.10	\$ 70.10 ✓
4	1	RHS Front Door / DD	\$ 1,387.50	\$ 1,387.50 ✓
5	2	RHS Front Door Hinge - BT	\$ 123.50	\$ 247.00 ✓
6	1	RHS Front Door Lock - BT	\$ 192.30	\$ 192.30 ✓
7	1	RHS Front Door Lock Catch - BT	\$ 75.70	\$ 75.70 ✓
8	1	RHS Front Door Handle Outer - CNT	\$ 67.20	\$ 67.20 ✓
9	1	RHS Front Door Handle Bracket - X NN	\$ 87.50	\$ 87.50 X
10	1	RHS Front Door Handle Pocket X NN	\$ 56.50	\$ 56.50 X
11	1	RHS Front Door Power Window Switch X NN	\$ 133.80	\$ 133.80 X
12	1	RHS Front Door Rod Key Lock X NN	\$ 89.80	\$ 89.80 X
13	1	RHS Front Door Weatherstrip - TN	\$ 103.60	\$ 103.60 ✓
14	1	RHS Front Door Window Glass X NN	\$ 259.00	\$ 259.00 X
15	1	RHS Front Door Window Glass Weatherstrip X NN	\$ 167.70	\$ 167.70 X
16	1	RHS Front Door Power Window Regulator - BT	\$ 110.50	\$ 110.50 ✓
17	1	RHS Front Door Power Window Regulator Motor - BR	\$ 707.30	\$ 707.30 445-41
18	1	RHS Front Door Inner Trim Board - BR	\$ 524.60	\$ 524.60 ✓
19	1	RHS Front Door Outer Molding X NN	\$ 108.50	\$ 108.50 X
20	1	RHS Front Door Hardness X NN	\$ 558.60	\$ 558.60 X
21	1	RHS Sliding Door / DD	\$ 1,688.20	\$ 1,688.20 1281.70
22	1	RHS Sliding Door Inner Trim Board X NN	\$ 786.80	\$ 786.80 X
23	1	RHS Sliding Door Handle - X NN	\$ 78.10	\$ 78.10 X
24	1	RHS Sliding Door Center Roller X NN	\$ 142.20	\$ 142.20 X
25	1	RHS Sliding Door Upper Roller X NN	\$ 65.10	\$ 65.10 X
26	1	RHS Sliding Door Lower Roller X NN	\$ 158.10	\$ 158.10 X
27	1	RHS Sliding Door Stopper X NN	\$ 38.00	\$ 38.00 X
28	1	RHS Sliding Door Weatherstrip X NN	\$ 169.80	\$ 169.80 X
29	1	RHS Sliding Door Lower Dovetail X NN	\$ 42.00	\$ 42.00 X
30	1	RHS Sliding Door Window Glass X NN	\$ 224.60	\$ 224.60 X
31	1	RHS Roof Drip Weatherstrip X NN	\$ 126.20	\$ 126.20 X
32	1	RHS Rocket Panel Outer X R	\$ 1,836.10	\$ 1,836.10 X
33	1	Dashboard X NN	\$ 1,373.10	\$ 1,373.10 X
34	1	Petrol Diesel Tank Cover - BT	\$ 156.90	\$ 156.90 ✓
35	1	RHS Front Knuckle X NN	\$ 392.40	\$ 392.40 X
36	1	RHS Front Absorber X NN	\$ 288.50	\$ 288.50 X
37	1	RHS Front Wheel Bearing - Janned	\$ 385.80	\$ 385.80 260
38	1	RHS Rear Wheel Bearing X NN	\$ 386.60	\$ 386.60 X
39	1	RHS Headlamp X NN	\$ 625.00	\$ 625.00 X

Total for spare parts

5507.71
- 10%
4956.93

Special Nett

1	10	RHS Front Fender Shield Clip X NN	\$	8.00	\$	80.00	X
2	10	RHS Front Door Inner Trim Board Clip / NK	\$	9.00	\$	90.00	30 ✓
3	10	RHS Sliding Door Inner Trim Board Clip X NN	\$	9.00	\$	90.00	X
4	1	RHS Front Rim X NN	\$	420.00	\$	420.00	X
5	1	RHS Front Tyre X NN	\$	380.00	\$	380.00	X
6	1	Window Sealant X / NK	\$	35.50	\$	35.50	✓

Total for SP \$ 1,095.50

Sub-Total for Parts : \$ 11,395.37

65.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention	\$	1,500.00 800
2		To putty and spray paint on all accident damage parts and other accident	\$	1,200.00 800
3		To check wiring system to facilitate repair and refit the same	\$	150.00 30
4		Apply rust proofing on the adjacent panels	\$	60.00 30
5		Reset engine management system with diagnostic fault	\$	80.00 X
6		To supply under coating / putty on parts replaced	\$	80.00 30
7		To conduct wheel alignment	\$	180.00 60
8		To perform water seepage test after repair	\$	150.00 30
10		To remove and replace windscreen	\$	200.00 150 120
12		Dismantle and transfer door fitting and mechanism to new door/facilitate repair	\$	180.00 120

Steve (LKK) NK NK
3/6/20, 11.00am
L/S
ny AL ny
5 dly

TOTAL AMOUNT : \$ 3,780.00

OVERALL COST: \$ 15,175.37

P- 4956.93
N- 65.50
L- 2020
Supp- 115.91
7157.44
L/S- 5725.95
= 5750

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

GOT 30655

Vehicle No: ~~SMR 2079T~~Model: ~~MERC CLA180~~Chassis No: ~~WDD1183842N000832~~

Year of manufacturing:

Steve 4/6/20

S/No	Qty	Supplementary	Unit Price	Amount
1	21	Door Inner White Board / DR	\$ 38.90	\$ 77.80
				<u>38.90</u>
				<u>77.80</u>
				-10%
				<u>7.78</u>
Total for spare parts				<u>70.02</u>

Special Nett

1	1	Speaker / DR (Find PH)	\$ 101.50	\$ 80.00
---	---	------------------------	-----------	----------

Total for SP	\$	80.00
Sub-Total for Parts :	\$	150.02

35.01
80
115.01