



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0016/05/20
M/S : TRANSPEED CARGO (S) PTE LTD

Page : 1/2
Date : 29/05/2020

THIRD PARTY CLAIM

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBE625Y - NISSAN URVAN
INSURED : TRANSPEED CARGO (S) PTE LTD
DATE OF ACCIDENT : 29/05/2020
POLICY NO : MOMVC000007910

ENGINE# :
CHASSIS# :

not Admin
1/6/20
1/5 6400
5 days

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

Qty	U/Cost	U/Price	Total
	\$	\$	\$
Netts Items			
1 rear boot	10 2264.60	2264.60	2,264.60
2 rear boot Nissan logo	10 65.70	65.70	65.70
3 rear boot NV350 emblem	10 101.30	101.30	101.30
4 rear boot urvan emblem	10 59.70	59.70	59.70
5 rear boot number plate lamp chrome garnish	10 511.40	511.40	511.40
6 rear lamp assembly LH & RH	20 209.80	209.80	419.60
7 rear bumper	10 600.50	600.50	600.50
8 rear bumper clips	80 5.10	5.10	408.00
9 rear boot rubber seal	10 127.00	127.00	127.00
10 rear boot lock center	10 256.70	256.70	256.70
11 rear boot side lock w/spring L & R	20 48.00	48.00	96.00
12 rear bumper side catch L & R	20 48.00	48.00	96.00
13 rear end panel lock lower catch	10 58.00	58.00	58.00
14 rear bumper reinforcement inner step panel	10 178.00	178.00	178.00
15 rear end panel (outer)	10 168.00	168.00	168.00
16 rear end panel (inner)	10 411.80	411.80	411.80
17 rear boot rubber side stopper L & R	20 11.00	11.00	22.00
18 rear boot inner center carpet garnish	10 160.00	160.00	160.00
19 rear boot inner center carpet garnish clips	160 5.10	5.10	816.00
20 rear boot inner center metal cover	10 109.00	109.00	109.00
21 rear rocker panel top aluminium bar	10 280.00	280.00	280.00
22 rear boot damper L & R	20 205.90	205.90	411.80
23 rear boot hinge L & R	20 52.00	52.00	104.00
24 rear bumper side retainer clip L & R	60 14.00	14.00	84.00
25 rear wiper motor inner cover	10 65.00	65.00	65.00
26 rear boot number plate lamp L & R	20 78.00	78.00	156.00

6,928.50

10%

1-8919.1
102
5327.15



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0016/05/20

Page : 2/2
Date : 01/06/2020

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Total Nett				
Special Nett Items				
1 rear boot 70km/h sticker <i>nee</i>	1@	15.00	15.00	15.00 <i>10</i>
2 rear boot 8 pax sticker <i>nee</i>	1@	15.00	15.00	15.00 <i>10</i>
3 rear number plate (yellow) <i>sed</i>	1@	40.00	40.00	40.00 <i>20</i>
4 rear bumper parking sensor <i>should</i>	1@	200.00	200.00	200.00 <i>200</i>
5 rear boot carpet floorboard (whole piece) <i>cm</i>	1@	580.00	580.00	580.00 <i>500</i>
6 rear windscreen sealant <i>nee</i>	1@	45.00	45.00	45.00 <i>40</i>
				895.00

Total S/Nett

Labour & Misc

1 Remove and install rear windscreen.	150.00 <i>120</i>
2 Remove and install rear boot, rear bumper, rear lamp Assembly L & R, Rear bumper enforcement. Cut out and renew rear end panel inner and outer, knocking rear fender L & R, rear fender inner L & R. Restraighten body and chassis.	1,200.00 <i>800</i>
3 Spray Painting	1,200.00 <i>900</i>
4 Remove Rear boot Carpet and lining.	80.00 <i>40</i>
5 Check wiring system.	25.00 <i>✓</i>
6 Renew rear parking sensor	80.00 <i>50</i>
	2,735.00
	0.00
	\$2,735.00

Total Labour

Nett Total Before Gst

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-5327-19
S.W 780.00
L-1535.00
8042.19
6437