



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :

Page : 1/2

Our Ref : TP0016/05/20

Date : 29/05/2020

THIRD PARTY CLAIM

M/S : TRANSPEED CARGO (S) PTE LTD

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : GBE625Y - NISSAN URVAN
INSURED : TRANSPEED CARGO (S) PTE LTD
DATE OF ACCIDENT : 29/05/2020
POLICY NO : MOMVC000007910

ENGINE# :
CHASSIS# :

*not Admin
1/6/20
1/5 6400
5 days*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

Qty	U/Price	U/Price	Total
	\$	\$	\$
Netts Items			
1 rear boot	1@ 2264.60	2264.60	2,264.60
2 rear boot Nissan logo	1@ 65.70	65.70	65.70
3 rear boot NV350 emblem	1@ 101.30	101.30	101.30
4 rear boot urvan emblem	1@ 59.70	59.70	59.70
5 rear boot number plate lamp chrome garnish	1@ 511.40	511.40	511.40
6 rear lamp assembly LH & RH	2@ 209.80	209.80	419.60
7 rear bumper	1@ 600.50	600.50	600.50
8 rear bumper clips	8@ 5.10	5.10	40.80
9 rear boot rubber seal	1@ 127.00	127.00	127.00
10 rear boot lock center	1@ 256.70	256.70	256.70
11 rear boot side lock w/spring L & R	2@ 48.00	48.00	96.00
12 rear bumper side catch L & R	2@ 48.00	48.00	96.00
13 rear end panel lock lower catch	1@ 58.00	58.00	58.00
14 rear bumper reinforcement inner step panel	1@ 178.00	178.00	178.00
15 rear end panel (outer)	1@ 168.00	168.00	168.00
16 rear end panel (inner)	1@ 411.80	411.80	411.80
17 rear boot rubber side stopper L & R	2@ 11.00	11.00	22.00
18 rear boot inner center carpet garnish	1@ 160.00	160.00	160.00
19 rear boot inner center carpet garnish clips	16@ 5.10	5.10	81.60
20 rear boot inner center metal cover	1@ 109.00	109.00	109.00
21 rear rocker panel top aluminium bar	1@ 280.00	280.00	280.00
22 rear boot damper L & R	2@ 205.90	205.90	411.80
23 rear boot hinge L & R	2@ 52.00	52.00	104.00
24 rear bumper side retainer clip L & R	6@ 14.00	14.00	84.00
25 rear wiper motor inner cover	1@ 65.00	65.00	65.00
26 rear boot number plate lamp L & R	2@ 78.00	78.00	156.00
			6,928.50

10%

6,928.50

*2-8919.1
102
5327.1*



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0016/05/20

Page : 2/2
Date : 01/06/2020

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost \$	U/Price \$	Total \$
Total Nett				
Special Nett Items				
1 rear boot 70km/h sticker <i>nee</i>	1@	15.00	15.00	15.00 <i>10</i>
2 rear boot 8 pax sticker <i>nee</i>	1@	15.00	15.00	15.00 <i>10</i>
3 rear number plate (yellow) <i>nee</i>	1@	40.00	40.00	40.00 <i>20</i>
4 rear bumper parking sensor <i>should</i>	1@	200.00	200.00	200.00 <i>200</i>
5 rear boot carpet floorboard(whole piece) <i>nee</i>	1@	580.00	580.00	580.00 <i>500</i>
6 rear windscreen sealant <i>nee</i>	1@	45.00	45.00	45.00 <i>40</i>
				895.00

Total S/Nett

Labour & Misc

1 Remove and install rear windscreen.	150.00 <i>120</i>
2 Remove and install rear boot, rear bumper, rear lamp Assembly L & R, Rear bumper enforcement. Cut out and renew rear end panel inner and outer, knocking rear fender L & R, rear fender inner L & R. Restraighten body and chassis.	1,200.00 <i>800</i>
3 Spray Painting	1,200.00 <i>900</i>
4 Remove Rear boot Carpet and lining.	80.00 <i>40</i>
5 Check wiring system.	25.00 <i>✓</i>
6 Renew rear parking sensor	80.00 <i>50</i>
	2,735.00
	0.00
	\$2,735.00

Total Labour

Nett Total Before Gst

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-5327-19
S.W 780.00
L-1535.00
over 6437