



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: INDIA INTERNATIONAL INSURANCE PTE	<b>Document No.</b>	: SQT20001705	<b>Page</b>	1
	64 CECIL STREET	<b>Date</b>	: 1. Jun 2020		
	#04-00 & #05-00 IOB BUILDING	<b>Customer No.</b>	: WZ1007		
	SINGAPORE 049711	<b>Svc Advisor</b>	:		
<b>Registration No</b>	: SLZ961Y	<b>Engine No</b>	: R16B25500530		
<b>Chassis No</b>	: MRHFC5650JT000478	<b>Date   Time</b>	: 1. Jun 2020 11:07:01 AM		
<b>Model</b>	: CIVIC 1.6 VTI YM2018	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: YEOH SENG CHUAN	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	:				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
71101-TEA-T00ZZ	FACEFR.BUMPER <i>2 in</i>	1	579.90	✓ 25	434.92	30.44	465.36
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE <i>gross</i>	1	19.70	✓ 25	14.77	1.03	15.80
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	? 25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>11</i>	1	10.40	X 25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER <i>na</i>	8	2.30	✓ 25	13.80	0.97	14.77
Sum Item					479.09	33.54	512.63
BOSUN	SUNDRIES <i>na</i>	1	50.00	20	50.00	3.50	53.50
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1200.00	650	1200.00	84.00	1284.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	900.00	450	900.00	63.00	963.00
Sum Labor					2150.00	150.50	2,300.50

TP DIRECT SETTLEMENT (J/NO: )  
OWNER: YEAH SEANG CHUAN  
OWNER INSURER: AVIVA INSURANCE  
ACC DATE: 29/05/2020  
SURVEYED BY:  
DATE:  
REF NO:  
TP INSURER: INDIA INSURANCE  
TP VEH: SHC3542Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Survey By: *Marcus LKK*  
Date & Time: *3/6/20 10.30am*  
Excess: *200*  
Status: *not authorized*  
Signature: *Take photo before painting 3 days*

Signature:  
Date:  
Total Amount: 2,629.09 184.04 2,813.13  
Total (Inclusive of GST) 2,813.13

Printed on 1/6/2020 4:28:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.