

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 03.06.20

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBK4400X**
MODEL : **MAXUS G10SL**
DATE OF ACCIDENT : 01.06.20
TIME OF ACCIDENT : 11:10HRS

TP Budget Direct.
Derise.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH <i>Dented</i>	1	\$ 1,899.00	\$ 1,899.00
2	FRONT DOOR BLACK STICKER RH <i>Neu</i>	1	\$ 125.10	\$ 125.10
3	FRONT DOOR OUTER STRIP RH <i>Neu</i>	1	\$ 107.30	\$ 107.30
4	FRONT DOOR HINGE RH <i>2</i>	2	\$ 73.20	\$ 146.40
5	FRONT DOOR INNER LOCK RH <i>for</i>	1	\$ 534.70	\$ 534.70
6	FRONT DOOR INNER TRIM RH <i>cancel</i>	1	\$ 890.20	\$ 890.20
7	FRONT DOOR LOCK CATCHER RH <i>2nd</i>	1	\$ 30.40	\$ 30.40
8	FRONT DOOR WEATHER STRIP RH <i>for</i>	1	\$ 171.20	\$ 171.20
9	FRONT DOOR POWER WINDOW MOTOR RH <i>Neu</i>	1	\$ 679.80	\$ 679.80
10	FRONT DOOR REGULATOR RH <i>Neu</i>	1	\$ 243.20	\$ 243.20
11	CENTER PILLAR (OUTER) RH <i>Neu</i>	1	\$ 307.70	\$ 307.70
12	CENTER PILLAR CHASSIS NUMBER PLATE <i>Neu</i>	1	\$ 240.30	\$ 240.30
13	SLIDING DOOR RH <i>Dented</i>	1	\$ 1,947.00	\$ 1,947.00
14	SLIDING DOOR BLACK STICKER RH <i>Neu</i>	1	\$ 120.40	\$ 120.40
15	SLIDING DOOR ROLLER RH (LOWER) <i>2nd</i>	1	\$ 332.70	\$ 332.70
16	SLIDING DOOR LOCK CATCHER RH <i>for</i>	1	\$ 40.00	\$ 40.00
17	SLIDING DOOR INNER LOCK RH <i>2nd</i>	1	\$ 536.40	\$ 536.40
18	SLIDING DOOR OUTER STRIP RH <i>for</i>	1	\$ 137.60	\$ 137.60
19	SLIDING DOOR STOPPER <i>Neu</i>	1	\$ 64.30	\$ 64.30
20	SLIDING DOOR FRAME WEATHER STRIP RH <i>Neu</i>	1	\$ 386.50	\$ 386.50

TOTAL PRICE \$ 8,940.20
LESS 10% \$ 894.02
SUB TOTAL PRICE \$ 8,046.18

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SEALANT RH <i>Neu</i>	1	\$ 150.00	\$ 150.00
2	FRONT DOOR INNER TRIM CLIP RH (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00
3	FRONT DOOR LTA SETICKER (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBK4400X**
 MODEL : **MAXUS G10SL**
 DATE OF ACCIDENT : 01.06.20
 TIME OF ACCIDENT : 11.10HRS

4	SLIDING DOOR SEALANT RH <i>Alm</i>	1	\$ 150.00	\$ 150.00	x
5	SLIDING DOOR INNER TRIM RIVERT RH (SET) <i>Alm</i>	1	\$ 80.00	\$ 80.00	20
6	SLIDING DOOR STEP PANEL GARNISH CLIP RH (SET) <i>Alm</i>	1	\$ 40.00	\$ 40.00	x
7	SLIDING DOOR WINDOW PLATE SEALANT <i>Alm</i>	1	\$ 150.00	\$ 150.00	x
8	SLIDING DOOR WINDOW PLATE INNER SEAL <i>Alm</i>	1	\$ 60.00	\$ 60.00	x
9	SLIDING DOOR INNER STANDARD STEEL TRIM (SEPC) <i>Alm</i>	1	\$ 650.00	\$ 650.00	x
10	CENTER PILLAR BLACK STICKER <i>Alm</i>	1	\$ 180.00	\$ 180.00	+

TOTAL \$ 1,560.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	400
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	500
3	TUFF COAT	\$ 250.00	x
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	x
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	x
7	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	40
8	REMOVE & REINSTALL FRONT WINDOW GLASS RH	\$ 80.00	40
9	REMOVE AND REFIX SLIDING DOOR INNER TRIM PLATE	\$ 80.00	40
10	TRANSFER SLIDING DOOR WINDOW PANEL	\$ 100.00	x
11	REMOVE & REINSTALL SLIDING DOOR GLASS RH	\$ 80.00	x
12	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 5,120.00

TO : BUDGET DIRECT MOTOR CLAIMS DEPTS
VEHICLE NO : GBK4400X
MODEL : MAXUS G10SL
DATE OF ACCIDENT : 01.06.20
TIME OF ACCIDENT : 11.10HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,606.18
TOTAL LABOUR COST : \$ 5,120.00
TOTAL REPAIR COST : \$ 14,726.18

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
SERVICE ADVISOR
ABBY
HP : 9856 4815

Adnan Lj
L/S 03/06/20
04 Days

total: 488045

L/S: 3.9K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: